Appendix C

Public ROW Surveys

Draft


LOCATION PRIORITY
#1 TRANSPORTATION FACILITIES
#2 ACCESS TO GOVERNMENT FACILITIES
#3 ACCESS TO PUBLIC ACCOMMODATIONS
#4 ACCESS TO PLACES OF EMPLOYMENT
#5 AREAS WITH HIGH LEVELS OF PEDESTRIAN TRAVEL

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C4	2nd Street / A Street SW	100	0	6
C4	2nd Street / A Street SE	100	0	6
C4	2nd Street / A Street NE	100	0	6
C4	3rd Street / A Street SW	100	0	6
C4	3rd Street / A Street SE	100	0	6
C4	4th Street / H Street	6	1	6
C4	4th Street / A Street NE	36	6	6
C4	4th Street / A Street NW	6	1	6
C4	4th Street / A Street SE	36	6	6
C4	4th Street / A Street SW	100	0	6
C4	5th Street / A Street E	36	6	6
C4	5th Street / A Street W	36	6	6
C5	6th Street / A Street SE	6	1	6
C4	6th Street / A Street SW	36	6	6
C5	7th Street / A Street SE	100	0	6
C5	7th Street / A Street SW	100	0	6
C4	A Street / Camelia Way NE	100	0	6
C4	A Street / Camelia Way NW	100	0	6
C11	Action Way / Elk Hills Drive N	6	1	6
C11	Action Way / Elk Hills Drive S	6	1	6
C10	Adare Way / Fermoy Way NW	36	6	6
C10	Adare Way / Fermoy Way NE	36	6	6
C10	Adare Way / Fermoy Way SE	36	6	6
C10	Adare Way / Fermoy Way SW	36	6	6
C10	Adare Way / West Stockton Boulevard NW	36	6	6
C10	Adare Way / West Stockton Boulevard SW	36	6	6
C9	Aldwych Court / Maugham Drive NW	100	0	6
C9	Aldwych Court / Maugham Drive NE	100	0	6
C6	Alice Rae Circle / Carr Way NE	36	6	6
C6	Alice Rae Circle / Carr Way NW	36	6	6
C6	Alice Rae Circle / Carr Way SE	36	6	6
C6	Alice Rae Circle / Carr Way SW	36	6	6
C4	Allport Drive / Driscol Drive South NE	36	6	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C4	Allport Drive / Driscol Drive South NW	36	6	6
C4	Allport Drive / Driscol Drive North NW	36	6	6
C4	Allport Drive / Driscol Drive N SW	36	6	6
C4	Allport Drive / Mc Tucker Drive NW	36	6	6
C4	Allport Drive / Mc Tucker Drive SW	36	6	6
C4	Allport Drive / Wristen Way NE	36	6	6
C4	Allport Drive / Wristen Way NW	36	6	6
C9	Almanor Way / Canyon Creek Way N	6	1	6
C9	Almanor Way / Canyon Creek Way S	6	1	6
C6	Alpen Rose Way / Daisy Drive SE	100	0	6
C6	Alpen Rose Way / Daisy Drive SW	100	0	6
C6	Alpen Rose Way / Daisy Drive NW	100	0	6
C6	Alpen Rose Way / Sparrow Drive SE	100	0	6
C6	Alpen Rose Way / Sparrow Drive NE	100	0	6
C11	Alta Vista Court / Emerald Vista Drive SW	36	6	6
C11	Alta Vista Court / Emerald Vista Drive NW	36	6	6
C9	Amador Avenue / Bernier Circle NE	6	1	6
C9	Amador Avenue / Bernier Circle SW	6	1	6
C7	Amador Avenue / Carol Drive NE	6	1	6
C7	Amador Avenue / Carol Drive SW	30	5	6
C9	Amador Avenue / Nathaniel Avenue	6	1	6
C9	Amador Avenue / Ron Way NE	6	1	6
C9	Amador Avenue / Ron Way SW	6	1	6
C7	Amador Way / North Lincoln Way NE	6	1	6
C7	Amador Way / North Lincoln Way NW	6	1	6
C7	Amador Way / North Lincoln Way SE	6	1	6
C7	Amador Way / North Lincoln Way SW	6	1	6
C13	Amberhill Avenue / Bentwood Drive	6	1	6
C9	Ambrogio Way / Carillion Boulevard NE	100	0	6
C9	Ambrogio Way / Carillion Boulevard SE	100	0	6
C10	Arlene Court / Fermoy Way SE	100	0	6
C10	Arlene Court / Fermoy Way NE	100	0	6
C11	Armstrong Way / Holmisdale Way	6	1	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C9	Arnett Way / Colmore Way NW	6	1	6
C9	Arnett Way / Colmore Way SE	6	1	6
C9	Arnett Way / Conwell Court N	6	1	6
C9	Arnett Way / Conwell Court S	6	1	6
C9	Arnett Way / Findon Court NW	6	1	6
C9	Arnett Way / Findon Court SE	6	1	6
C9	Arnett Way / Stenton Way	6	1	6
C9	Ashboro Lane / Lyonia Drive E	6	1	6
C9	Ashboro Lane / Lyonia Drive W	6	1	6
C6	Ashley Way / Sunshine Drive NW	6	1	6
C6	Ashley Way / Sunshine Drive SW	6	1	6
C12	Athy Court / Fermoy Way NE	36	6	6
C12	Athy Court / Fermoy Way SE	36	6	6
C11	Avondale Court / Emerald Vista Drive NW	36	6	6
C11	Avondale Court / Emerald Vista Drive SW	36	6	6
C9	Ayers Avenue / Nathaniel Avenue	6	1	6
C4	B Street / 2nd Street NE	100	0	2
C4	B Street / 2nd Street SW	100	0	2
C4	B Street / 2nd Street NW	100	0	2
C4	B Street / 3rd Street NW	6	1	6
C4	B Street / 3rd Street SW	36	6	6
C4	B Street / 4th Street NE	6	1	6
C4	B Street / 4th Street NW	3	1	3
C4	B Street / 4th Street SE	100	0	3
C4	B Street / 4th Street SW	3	1	3
C4	B Street / 5th Street NE	100	0	6
C4	B Street / 5th Street NW	6	1	6
C4	B Street / 5th Street SE	100	0	6
C4	B Street / 5th Street SW	36	6	6
C5	B Street / 6th Street NE	36	6	6
C5	B Street / 6th Street NW	6	1	6
C5	B Street / 6th Street SE	6	1	6
C4	B Street / 6th Street SW	6	1	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Gnd	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C5	B Street / 7th Street NE	6	1	6
C5	B Street / 7th Street NW	36	6	6
C5	B Street / 7th Street SE	36	6	6
C5	B Street / 7th Street SW	36	6	6
C5	B Street / Lincoln Way N	36	6	6
C5	B Street / Lincoln Way SW	36	6	6
C9	Baker Court / Roundstone Drive NW	100	0	6
C9	Baker Court / Roundstone Drive NE	100	0	6
C11	Balboa Court / Emerald Vista Drive NW	36	6	6
C11	Balboa Court / Emerald Vista Drive SW	36	6	6
C9	Barsetti Court / Stoneygate Drive NW	100	0	6
C9	Barsetti Court / Stoneygate Drive NE	100	0	6
C11	Bateman Way / Hepworth Way E	6	1	6
C11	Bateman Way / Hepworth Way W	6	1	6
C11	Bateman Way / Millson Court E	18	3	6
C11	Bateman Way / Millson Court W	6	1	6
C13	Bay Heights Drive / Beaver Park Way E	6	1	6
C13	Bay Heights Drive / Beaver Park Way W	6	1	6
C11	Bay Landing Way / Bay Terrace Drive N	6	1	6
C11	Bay Landing Way / Bay Terrace Drive S	6	1	6
C11	Bay Landing Way / Howard Court E	6	1	6
C11	Bay Landing Way / Howard Court W	6	1	6
C11	Bay Landing Way / Marine Bay Drive E	6	1	6
C11	Bay Landing Way / Marine Bay Drive W	6	1	6
C11	Bay Shore Drive / Bay Landing Way N	6	1	6
C11	Bay Shore Drive / Bay Landing Way S	6	1	6
C11	Bay Shore Drive / Blackwell Way E	6	1	6
C11	Bay Shore Drive / Blackwell Way SE	6	1	6
C11	Bay Shore Drive / Blackwell Way W	6	1	6
C13	Bay Shore Drive / Lake Park Avenue E	5	1	5
C13	Bay Shore Drive / Lake Park Avenue W	15	3	5
C13	Bay Shore Drive / Park Heights Drive N	6	1	6
C13	Bay Shore Drive / Park Heights Drive S	6	1	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C11	Bay Shore Drive / Piermont Court NE	6	1	6
C11	Bay Shore Drive / Piermont Court NW	6	1	6
C11	Bay Shore Drive / Piermont Court SE	6	1	6
C11	Bay Shore Drive / Piermont Court SW	6	1	6
C11	Bay Terrace Drive / Bay Vista Court E	2	1	2
C11	Bay Terrace Drive / Bay Vista Court W	2	1	2
C11	Beaver Park Way / Elk Hills Drive NW	100	0	6
C11	Beaver Park Way / Elk Hills Drive SE	36	6	6
C11	Beaver Park Way / Elk Hills Drive SW	36	6	6
C13	Beaver Park Way / Golden Heights N	6	1	6
C13	Beaver Park Way / Golden Heights S	6	1	6
C11	Beaver Park Way / Moose Creek Way N	6	1	6
C11	Beaver Park Way / Moose Creek Way S	6	1	6
C11	Beaver Park Way / Olive Canyon Drive N	4	2	2
C11	Beaver Park Way / Olive Canyon Drive S	4	2	2
C11	Beaver Way / Elk Hills Drive NE	6	1	6
C11	Beeler Way / Cottrell Way	6	1	6
C11	Beeler Way / Jordine Way E	6	1	6
C11	Beeler Way / Jordine Way W	6	1	6
C11	Beeler Way / Norbury Way E	6	1	6
C11	Beeler Way / Norbury Way W	6	1	6
C12	Belfast Court / Fermoy Court NW	36	6	6
C12	Belfast Court / Fermoy Court SW	36	6	6
C9	Benteen Way / Hansard Court N	6	1	6
C9	Benteen Way / Hansard Court S	6	1	6
C11	Benteen Way / Lanigan Court N	12	2	6
C11	Benteen Way / Lanigan Court S	12	2	6
C9	Bernier Circle / Ewell Court E	6	1	6
C9	Bernier Circle / Ewell Court W	6	1	6
C9	Bernier Circle / Nathaniel Avenue N	6	1	6
C9	Bernier Circle / Nathaniel Avenue S	6	1	6
C4	Big Jake Way / Matthew Court NE	36	6	6
C4	Big Jake Way / Matthew Court NW	36	6	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C4	Big Jake Way / Wagon Way NW	12	6	2
C4	Big Jake Way / Wagon Way SW	12	6	2
C9	Blackhurst Drive / Tottenham Drive NW	100	0	6
C9	Blackhurst Drive / Tottenham Drive SW	100	0	6
C9	Blackhurst Drive / Whitechapel Drive NE	100	0	6
C9	Blackhurst Drive / Whitechapel Drive SE	100	0	6
C11	Blackwell Way / Charsley Way N	6	1	6
C11	Blackwell Way / Charsley Way SE	6	1	6
C11	Blackwell Way / Charsley Way SW	6	1	6
C11	Blackwell Way / Fawcett Court N	18	3	6
C11	Blackwell Way / Fawcett Court S	6	1	6
C11	Blackwell Way / Fawcett Court W	6	1	6
C6	Bluebell Court . Daisy Drive SE	100	0	6
C6	Bluebell Court / Daisy Drive SW	100	0	6
C5	Boessow Road / Crystal Way SE	100	0	6
C5	Boessow Road / Crystal Way NE	100	0	6
C3	Bonanza Drive / Chisolm Trail NE	36	6	6
C3	Bonanza Drive / Chisolm Trail NW	36	6	6
C4	Branding Iron Way / Stetson Way	6	1	6
C13	Breakers Drive / Bay Terrace Drive NE	6	1	6
C13	Breakers Drive / Bay Terrace Drive NW	6	1	6
C13	Breakers Drive / Bay Terrace Drive SE	6	1	6
C13	Breakers Drive / Bay Terrace Drive SW	6	1	6
C13	Breakers Drive / Lewins Court E	6	1	6
C13	Breakers Drive / Lewins Court W	6	1	6
C13	Breakers Drive / Park Terrace Drive NW	6	1	6
C11	Breakers Drive / Park Terrace Drive SW	6	1	6
C3	Bridal Path / Chisholm Trail	6	1	6
C6	Brodie Drive / Banff Court NE	6	1	6
C6	Brodie Drive / Banff Court NW	6	1	6
C6	Brodie Drive / Emerald Court E	24	4	6
C6	Brodie Drive / Emerald Court W	24	4	6
C6	Brodie Drive / Emerald Drive E	24	4	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C6	Brodie Drive / Emerald Drive W	24	4	6
C6	Brodie Drive / Oberlin Drive NW	6	1	6
C6	Brodie Drive / Oberlin Drive SW	6	1	6
C6	Brodie Drive / Royal Court E	24	4	6
C6	Brodie Drive / Royal Court W	24	4	6
C11	Buttercup Circle / Vintage Oak Avenue NNE	36	6	6
C11	Buttercup Circle / Vintage Oak Avenue NSE	36	6	6
C11	Buttercup Circle / Vintage Oak Avenue SNE	36	6	6
C11	Buttercup Circle / Vintage Oak Avenue SSE	36	6	6
C4	C Street School Crosswalk	100	0	5
C4	C Street Denny's Midlblock Crosswalk	100	0	5
C4	C Street / 2nd Street NE	100	0	5
C4	C Street / 2nd Street NW	100	0	5
C4	C Street / 2nd Street SE	100	0	5
C4	C Street / 2nd Street SW	100	0	5
C4	C Street / 3rd Street NE	100	0	5
C4	C Street / 3rd Street NW	100	0	5
C4	C Street / 3rd Street SE	5	1	5
C4	C Street / 3rd Street SW	100	0	5
C4	C Street / 4th Street NE	100	0	3
C4	C Street / 4th Street NW	100	0	3
C4	C Street / 4th Street SE	100	0	3
C4	C Street / 4th Street SW	100	0	3
C4	C Street / 5th Street NE	100	0	3
C4	C Street / 5th Street NW	100	0	3
C4	C Street / 5th Street SE	100	0	3
C4	C Street / 5th Street SW	100	0	3
C5	C Street / 6th Street NE	18	6	3
C5	C Street / 6th Street NW	100	0	3
C5	C Street / 6th Street SE	3	1	3
C5	C Street / 6th Street SW	100	0	3
C5	C Street / 7th Street NE	18	6	3
C5	C Street / 7th Street NW	18	6	3

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C5	C Street / 7th Street SE	18	6	3
C5	C Street / 7th Street SW	18	6	3
C5	C Street / Civic Drive NE	100	0	1
C5	C Street / Civic Drive NW	100	0	1
C5	C Street / Civic Drive SE	6	6	1
C5	C Street / Civic Drive SW	6	6	1
C5	C Street / Lincoln Way NE	100	0	3
C5	C Street / Lincoln Way NW	18	6	3
C5	C Street / Lincoln Way SE	18	6	3
C5	C Street / Lincoln Way SW	18	6	3
C5	C Street / Maple Street SE	100	0	3
C5	C Street / Maple Street SW	100	0	3
C5	C Street / Maple Street N	100	0	3
C5	C Street / Market Street NE	100	0	3
C5	C Street / Market Street NW	18	6	3
C5	C Street / Wagon Way NE	36	6	6
C5	C Street / Wagon Way SE	36	6	6
C9	Canyon Creek Way / Cold Brook Way E	36	6	6
C9	Canyon Creek Way / Cold Brook Way W	36	6	6
C9	Canyon Creek Way / Summit Lakes N	36	6	6
C9	Canyon Creek Way / Summit Lakes S	36	6	6
C2	Cardoso Court / Maria Way SE	36	6	6
C2	Cardoso Court / Maria Way SW	36	6	6
C2	Cardoso Drive / Fernando Way SE	36	6	6
C2	Cardoso Drive / Fernando Way NE	36	6	6
C2	Cardoso Drive / Maria Way NE	36	6	6
C2	Cardoso Drive / Maria Way NW	36	6	6
C2	Cardoso Drive / Vineyards Court NE	36	6	6
C2	Cardoso Drive / Vineyards Court NW	36	6	6
C9	Carillion / Vintage Oak N	36	6	6
C9	Carillion / Vintage Oak S	36	6	6
C9	Carillion Boulevard / Chelsham Avenue NE	36	6	6
C9	Carillion Boulevard / Chelsham Avenue NW	36	6	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C9	Carillion Boulevard / Chelsham Avenue SE	12	2	6
C9	Carillion Boulevard / Chelsham Avenue SW	24	4	6
C9	Carillion Boulevard / Vauxhall Avenue NE	36	6	6
C9	Carillion Boulevard / Vauxhall Avenue NW	36	6	6
C9	Carillion Boulevard / Vauxhall Avenue SE	24	4	6
C9	Carillion Boulevard / Vauxhall Avenue SW	24	4	6
C9	Carol Drive / Ashboro Lane E	36	6	6
C9	Carol Drive / Ashboro Lane N	36	6	6
C9	Carol Drive / Delane Drive N	36	6	6
C9	Carol Drive / Delane Drive S	36	6	6
C5	Caroline Avenue School Crosswalk	100	0	5
C5	Caroline Avenue / Chabolla Avenue NE	100	0	3
C5	Caroline Avenue / Chabolla Avenue NW	100	0	3
C5	Carlone Avenue / Chabolla Avenue SW	100	0	3
C5	Caroline Avenue / Civic Drive NE	100	0	1
C4	Caroline Avenue / Civic Drive NW	100	0	1
C5	Caroline Avenue / Civic Drive SE	100	0	1
C5	Caroline Avenue / Civic Drive SW	1	1	1
C5	Caroline Avenue / Fairway Way NW	100	0	5
C5	Caroline Avenue / Fairway Way SW	100	0	5
C5	Caroline Avenue / Maple Street NE	12	6	2
C5	Caroline Avenue / Maple Street NW	12	6	2
C5	Caroline Avenue / Maple Street SE	100	0	2
C5	Caroline Avenue / Meladee Lane SE	30	6	5
C5	Caroline Avenue / Meladee Lane SW	30	6	5
C5	Caroline Avenue / Pine Street NW	100	0	5
C5	Caroline Avenue / Pine Street NE	30	6	5
C5	Caroline Avenue / Pine Street SE	30	6	5
C13	Carpinteria Drive / Linda Marie Court E	24	4	6
C13	Carpinteria Drive / Linda Marie Court W	24	4	6
C13	Carpinteria Drive / Park Terrace Drive N	24	4	6
C13	Carpinteria Drive / Park Terrace Drive S	36	6	6
C5	Casado Drive / Happy Court NE	5	1	5

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C5	Casado Drive / Happy Court SE	5	1	5
C11	Caversham Way / Malton Way NE	12	2	6
C11	Caversham Way / Malton Way SW	12	2	6
C11	Cedar Canyon Circle	12	2	6
C11	Cedar Canyon Circle / Black Oyn Court E	12	2	6
C11	Cedar Canyon Circle / Black Oyn Court W	12	2	6
C11	Cedar Canyon Circle SW	36	6	6
C9	Cedar Flat Avenue / Coburg Court N	36	6	6
C9	Cedar Flat Avenue / Coburg Court S	12	2	6
C9	Cedar Flat Avenue / Colson Court N	12	2	6
C9	Cedar Flat Avenue / Colson Court S	42	7	6
C9	Cedar Flat Avenue / Colson Way N	42	7	6
C9	Cedar Flat Avenue / Colson Way S	42	7	6
C11	Cedar Flat Way / Benteen Way	10	5	2
C11	Charsley Way / Piermont Way NW	18	3	6
C11	Charsley Way / Piermont Way S	18	3	6
C3	Chase Drive / Chisolm Trail NE	100	0	6
C3	Chase Drive / Chisolm Trail SW	36	6	6
C3	Chase Drive / Chisolm Trail SE	100	0	6
C9	Chelsham Avenue / Hamstead Drive SE	36	6	6
C9	Chelsham Avenue / Hamstead Drive SW	36	6	6
C9	Chelsham Avenue / Marengo NE	36	6	6
C9	Chelsham Avenue / Marengo SE	36	6	6
C9	Chelsham Avenue / Portland Lane NW	100	0	6
C9	Chelsham Avenue / Portland Lane NE	100	0	6
C9	Chelsham Avenue / Portland Lane SE	36	6	6
C9	Chelsham Avenue / Portland Lane SW	36	6	6
C9	Chelsham Avenue / Stoneygate Drive N	36	6	6
C9	Chelsham Avenue / Stoneygate Drive S	36	6	6
C9	Chelsham Avenue / Tottenham Drive NE	100	0	6
C9	Chelsham Avenue / Tottenham Drive NW	100	0	6
C9	Chelsham Avenue / Whitechapel Drive NE	100	0	6
C9	Chelsham Avenue / Whitechapel Drive NW	100	0	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Gnd	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C3	Chisolm Trail / Bonanza Drive NE	36	6	6
C3	Chisolm Trail / Bonanza Drive NW	36	6	6
C5	Church Street / Fairsite Court NE	36	6	6
C5	Church Street / Fairsite Court SE	36	6	6
C6	Cinnamon Drive / Sparrow Drive N	36	6	6
C6	Cinnamon Drive / Sparrow Drive S	36	6	6
C6	Cinnamon Drive / Sterling Oak Drive	36	6	6
C11	Cobble Hill Way / Cobble Way	18	3	6
C9	Cobble Hill Way / Summit Lakes Way N	6	3	2
C9	Cobble Hill Way / Summit Lakes Way S	6	3	2
C11	Cobble Way / Steep Rock Court E	18	3	6
C11	Cobble Way / Steep Rock Court W	24	4	6
C11	Cobble Way / Summit Lakes Court	24	4	6
C11	Cobden Way / Koralla Way NE	24	4	6
C11	Cobden Way / Koralla Way SW	24	4	6
C9	Cold Brook Way / Cedar Flat Avenue NE	24	4	6
C9	Cold Brook Way / Cedar Flat Avenue NW	24	4	6
C9	Cold Brook Way / Cedar Flat Avenue SE	24	4	6
C9	Cold Brook Way / Cedar Flat Avenue SW	24	4	6
C9	Colmore Way / Trammel Way E	24	4	6
C9	Colmore Way / Trammel Way W	24	4	6
C9	Colson Way / Arnett Way NW	24	4	6
C9	Colson Way / Arnett Way SE	24	4	6
C9	Colson Way / Cleland Court E	24	4	6
C9	Colson Way / Cleland Court W	24	4	6
C9	Colson Way / Tallega Court E	42	7	6
C9	Colson Way / Tallega Court W	24	4	6
C3	Corral Place / Bonanza Drive SW	36	6	6
C3	Corral Place / Bonanza Drive SE	36	6	6
C3	Corral Place / Tradepost Trail NNW	100	0	6
C3	Corral Place / Tradepost Trail NE	100	0	6
C3	Corral Place / Tradepost Trail S	100	0	6
C11	Cottrell Way / Presbury Way N	24	4	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C11	Cottrell Way / Presbury Way S	24	4	6
C2	Creekside Way / Kandy Street NW	30	6	5
C2	Creekside Way / Kandy Street SW	30	6	5
C2	Creekside Way / Kost NE	100	0	5
C2	Creekside Way / Kost NW	100	0	5
C6	Crescent Drive / Crescent Drive Court N	24	4	6
C6	Crescent Drive / Crescent Drive Court N	24	4	6
C6	Crescent Drive / Elm Avenue SE	100	0	6
C6	Crescent Drive / Elm Avenue SW	100	0	6
C2	Crow Creek Drive / 1st Street NE	36	6	6
C2	Crow Creek Drive / 1st Street SE	36	6	6
C2	Crow Creek Drive / Janine Court N	36	6	6
C2	Crow Creek Drive / Janine Court SE	36	6	6
C2	Crow Creek Drive / Janine Court SW	36	6	6
C5	Crystal Way / Franston Street N	18	3	6
C5	Crystal Way / Franston Street S	18	3	6
C4	D Street / 4th Street NE	100	0	6
C4	D Street / 4th Street SE	100	0	3
C4	D Street / 5th Street NE	18	6	3
C4	D Street / 5th Street NW	3	1	3
C4	D Street / 5th Street SE	18	6	3
C4	D Street / 5th Street SW	3	1	3
C5	D Street / 6th Street NE	36	6	6
C5	D Street / 6th Street NW	36	6	6
C5	D Street / 6th Street SE	36	6	6
C5	D Street / 6th Street SW	36	6	6
C5	D Street / 7th Street NE	18	6	3
C5	D Street / 7th Street NW	18	6	3
C5	D Street / Lincoln Way N	12	4	3
C5	D Street / Lincoln Way S	12	4	3
C6	Daisy Drive / Edelweiss Way SE	36	6	6
C6	Daisy Drive / Edelweiss Way NE	36	6	6
C4	Danny Drive / Dawn Circle NW	100	0	5

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C4	Danny Drive / Dawn Circle SW	100	0	5
C13	Dawnwood Drive / Amberhill Avenue N	24	4	6
C13	Dawnwood Drive / Amberhill Avenue S	24	4	6
C9	Delane Drive / Bernier Circle N	24	4	6
C9	Delane Drive / Bernier Circle S	24	4	6
C9	Delane Drive / Ron Way E	24	4	6
C9	Delane Drive / Ron Way W	24	4	6
C9	Denier Court / Vauxhall Avenue SW	36	6	6
C9	Denier Court / Vauxhall AveAvenue SE	36	6	6
C9	Di Maggio Court / Carillion Boulevard NE	100	0	6
C9	Di Maggio Court / Carillion Boulevard SE	100	0	6
C9	Dickens Drive / Hamstead Drive SE	100	0	6
C9	Dickens Drive / Hamstead Drive NW	100	0	6
C9	Dickens Drive / Marengo Road SW	100	0	6
C9	Dickens Drive / Marengo Road NW	100	0	6
C11	Doradell Way / Strathaven Way N	24	4	6
C11	Doradell Way / Strathaven Way S	24	4	6
C11	Doradell Way / Vanstom Court N	24	4	6
C11	Doradell Way / Vanstom Court S	24	4	6
C2	Downing Drive / Gaylon Way NE	36	6	6
C2	Downing Drive / Gaylon Way SW	36	6	6
C2	Downing Drive / Holly Court NW	36	6	6
C2	Downing Drive / Holly Court NE	36	6	6
C2	Downing Drive / Maria Way SE	36	6	6
C2	Downing Drive / Maria Way SW	36	6	6
C2	Downing Drive / Meadowview Drive NE	100	0	6
C2	Downing Drive / Meadowview Drive NW	100	0	6
C2	Downing Drive / Meadowview Drive SE	100	0	6
C2	Downing Drive / Meadowview Drive SW	100	0	6
C11	Duncraig Way / Armstrong Way N	24	4	6
C11	Duncraig Way / Armstrong Way S	24	4	6
C4	E Street / 2nd Street NE	6	1	6
C4	E Street / 2nd Street NW	36	6	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C4	E Street / 2nd Street SE	6	1	6
C4	E Street / 2nd Street SW	36	6	6
C4	E Street / 3rd Street NW	36	6	6
C4	E Street / 3rd Street SW	36	6	6
C4	E Street / 4th Street NE	100	0	6
C4	E Street / 4th Street SE	6	1	6
C5	E Street / 5th Street NE	100	0	6
C5	E Street / 5th Street NW	36	6	6
C5	E Street / 5th Street SE	100	0	6
C5	E Street / 5th Street SW	100	0	6
C5	E Street / 6th Street NE	36	6	6
C5	E Street / 6th Street NW	36	6	6
C5	E Street / 6th Street SE	36	6	6
C5	E Street / 6th Street SW	100	0	6
C4	E Street / Laborador Court SE	36	6	6
C4	E Street / Laborador Court SW	36	6	6
C5	E Street / Lincoln Way NW	12	6	2
C5	E Street / Lincoln Way SW	12	6	2
C4	E Street / Retriever Way East SE	36	6	6
C4	E Street / Retriever Way East SW	36	6	6
C4	E Street / Retriever Way West SW	36	6	6
C4	E Street / Retriever Way West SE	36	6	6
C4	West E Street / Spur Way SE	36	6	6
C4	West E Street / Spur Way SW	36	6	6
C4	West E Street / Stetson Way NE	36	6	6
C4	West E Street / Stetson Way NW	36	6	6
C4	West E Street / Wagon Way SW	36	6	6
C4	West E Street / Wagon Way SE	36	6	6
C4	West E Street / Wagon Way NE	36	6	6
C4	West E Street / Wagon Way NW	24	4	6
C4	West E Street / Village Run SE	36	6	6
C4	West E Street / Village Run SW	36	6	6
C10	East Stockton / Walnut Avenue NE	24	4	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C10	East Stockton / Walnut Avenue SE	24	4	6
C10	East Stockton / Winn Drive NE	20	4	5
C10	East Stockton / Winn Drive SE	20	4	5
C6	Edelweiss Way / Sparrow Drive SW	100	0	6
C6	Edelweiss Way / Sparrow Drive NW	100	0	6
	Edelweiss Way / West Elm Avenue NW	100	0	6
C6	Edelweiss Way / West Elm Avenue NE	100	0	6
C11	Elk Hills Drive / Jordine Way E	24	4	6
C11	Elk Hills Drive / Jordine Way W	24	4	6
C11	Elk Hills Drive / Marengo Road N	24	4	6
C11	Elk Hills Drive / Marengo Road S	24	4	6
C11	Elk Hills Drive / Norbury Way NE	24	4	6
C11	Elk Hills Drive / Norbury Way NW	24	4	6
C11	Elk Hills Drive / Norbury Way SE	24	4	6
C11	Elk Hills Drive / Norbury Way SW	24	4	6
C11	Elk Hills Drive / Parnel Way E	24	4	6
C11	Elk Hills Drive / Parnel Way W	24	4	6
C11	Elk Hills Drive	8	4	2
C11	Elk Hills Drive / Bateman Way E	24	4	6
C11	Elk Hills Drive / Bateman Way W	24	4	6
C11	Elk Hills Drive / Bay Shore Drive NE	8	4	2
C11	Elk Hills Drive / Bay Shore Drive NW	8	4	2
C11	Elk Hills Drive / Bay Shore Drive SE	8	4	2
C11	Elk Hills Drive / Bay Shore Drive SW	8	4	2
C11	Elk Hills Drive / Carillion Boulevard NE	24	4	6
C11	Elk Hills Drive / Carillion Boulevard NW	24	4	6
C11	Elk Hills Drive / Carillion Boulevard SE	24	4	6
C11	Elk Hills Drive / Carillion Boulevard SW	24	4	6
C11	Elk Hills Drive / Cobden Way E	24	4	6
C11	Elk Hills Drive / Cobden Way W	24	4	6
C11	Elk Hills Drive / Doradell Way NE	24	4	6
C11	Elk Hills Drive / Doradell Way SW	24	4	6
C11	Elk Hills Drive / Dutch Harbor Court E	24	4	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C11	Elk Hills Drive / Dutch Harbor Court W	24	4	6
C11	Elk Hills Drive / Elsworth Court E	24	4	6
C11	Elk Hills Drive / Elsworth Court SW	24	4	6
C11	Elk Hills Drive / Elsworth Court W	24	4	6
C11	Elk Hills Drive / Lampard Way E	8	4	2
C11	Elk Hills Drive / Lampard Way N	8	4	2
C11	Elk Hills Drive / Padbury Court E	24	4	6
C11	Elk Hills Drive / Padbury Court W	24	4	6
C11	Elk Hills Drive / Rossburn Way NE	24	4	6
C11	Elk Hills Drive / Rossburn Way NW	24	4	6
C11	Elk Hills Drive / Rossburn Way SE	24	4	6
C11	Elk Hills Drive / Rossburn Way SW	24	4	6
C11	Elk Hills Drive / Walnut Avenue NE	8	4	2
C11	Elk Hills Drive / Walnut Avenue SW	8	4	2
C11	Elk Hills Drive / Whitford Cout E	24	4	6
C11	Elk Hills Drive / Whitford Cout W	24	4	6
C6	West Elm Avenue / Ashley Way SE	36	6	6
C6	West Elm Avenue / Ashley Way SW	36	6	6
C6	West Elm Avenue / Grouse Drive E	24	4	6
C6	West Elm Avenue / Grouse Drive W	24	4	6
C6	West Elm Avenue / Oak E	24	4	6
C6	West Elm Avenue / Oak W	24	4	6
C6	West Elm Avenue / Robin Lane E	24	4	6
C6	West Elm Avenue / Robin Lane W	24	4	6
C6	West Elm Avenue / Sparrow Drive E	24	4	6
C6	West Elm Avenue / Sparrow Drive W	24	4	6
C6	Elm Avenue / Oak Avenue E	100	0	6
C6	Elm Avenue / Oak Avenue W	100	0	6
C6	Elm Avenue / Palin Avenue NE	100	0	6
C7	Elm Avenue / Palin Avenue NW	100	0	6
C7	Elm Avenue / Palin Avenue SE	100	0	6
C7	Elm Avenue / Palin Avenue SW	100	0	6
C7	Elm Avenue / Sunset Circle West NE	36	6	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C7	Elm Avenue / Sunset Circle East NE	36	6	6
C7	Elm Avenue / Sunset Circle West NW	36	6	6
C7	Elm Avenue / Sunset Circle East NW	36	6	6
C4	Emerald Drive / Almo Court NE	6	1	6
C4	Emerald Drive / Almo Court SE	6	1	6
C4	Emerald Drive / Brodie Drive SW	6	1	6
C4	Emerald Drive / Brodie Drive SE	6	1	6
C4	Emerald Drive / Brodie Drive NW	6	1	6
C4	Emerald Drive / Brodie Drive NE	6	1	6
C4	Emerald Drive / Ramon Drive NE	6	1	6
C4	Emerald Drive / Ramon Drive NW	6	1	6
C4	Emerald Drive / Ramon Drive SE	6	1	6
C4	Emerald Drive / Ramon Drive SW	6	1	6
C4	Emerald Drive / Spree Court NE	6	1	6
C4	Emerald Drive / Spree Court SE	6	1	6
C6	Emerald Drive / Trent Drive NE	6	1	6
C6	Emerald Drive / Trent Court NW	6	1	6
C6	Emerald Drive / Trent Drive SE	6	1	6
C6	Emerald Drive / Trent Court SW	6	1	6
C4	Emerald Drive / West A Street NE	6	1	6
C4	Emerald Drive / West A Street NW	6	1	6
C6	Emerald Oak Drive / Amor Court N	24	4	6
C6	Emerald Oak Drive / Amor Court S	24	4	6
C6	Emerald Oak Drive / Brodie Drive N	24	4	6
C6	Emerald Oak Drive / Brodie Drive S	24	4	6
C6	Emerald Oak Drive / Brodiewest Court N	24	4	6
C6	Emerald Oak Drive / Brodiewest Court S	24	4	6
C6	Emerald Oak Drive / Rossi Drive N	24	4	6
C6	Emerald Oak Drive / Rossi Drive S	24	4	6
C4	Emerald Oak Drive / West A Street E	24	4	6
C4	Emerald Oak Drive / West A Street W	24	4	6
C9	Emerald Vista / Los Flores Court N	20	4	5
C9	Emerald Vista / Los Flores Court S	20	4	5
C11	Emerald Vista / Twin Hills Drive NE	24	4	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C11	Emerald Vista / Twin Hills Drive SE	24	4	6
C11	Emerald Vista Drive / Birch Court N	24	4	6
C11	Emerald Vista Drive / Birch Court S	24	4	6
C10	Emerald Vista Drive / Cimmaron Court N	24	4	6
C10	Emerald Vista Drive / Cimmaron Court S	24	4	6
C11	Emerald Vista Drive / Elk Hills Drive NE	36	6	6
C11	Emerald Vista Drive / Elk Hills Drive NW	36	6	6
C11	Emerald Vista Drive / Elk Hills Drive SE	36	6	6
C11	Emerald Vista Drive / Elk Hills Drive SW	36	6	6
C11	Emerald Vista Drive / Moose Creek Way N	24	4	6
C11	Emerald Vista Drive / Moose Creek Way S	24	4	6
C10	Emerald Vista Drive / Prairie Court N	30	5	6
C10	Emerald Vista Drive / Prairie Court S	30	5	6
C11	Emerald Vista Drive / Twin Hills Drive N	30	5	6
C11	Emerald Vista Drive / Twin Hills Drive S	30	5	6
C11	Emerald Vista Drive / Walnut Avenue NE	30	5	6
C11	Emerald Vista Drive / Walnut Avenue NW	30	5	6
C11	Emerald Vista Drive / Walnut Avenue SE	30	5	6
C11	Emerald Vista Drive / Walnut Avenue SW	30	5	6
C10	Emerald Vista Drive / Willowgreen Circle N	30	5	6
C10	Emerald Vista Drive / Willowgreen Circle NN	30	5	6
C10	Emerald Vista Drive / Willowgreen Circle S	30	5	6
C10	Emerald Vista Drive / Willowgreen Circle SS	30	5	6
C4	F Street / 2nd Street NE	36	6	6
C4	F Street / 2nd Street NW	36	6	6
C4	F Street / 2nd Street SE	36	6	6
C4	F Street / 2nd Street SW	36	6	6
C4	F Street / 3rd Street NE	36	6	6
C4	F Street / 3rd Street NW	36	6	6
C4	F Street / 3rd Street SE	36	6	6
C4	F Street / 3rd Street SW	36	6	6
C4	F Street / 4th Street NE	36	6	6
C4	F Street / 4th Street NW	6	1	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C4	F Street / 4th Street SE	36	6	6
C4	F Street / 4th Street SW	100	0	6
C5	F Street / 5th Street NE	36	6	6
C5	F Street / 5th Street NW	36	6	6
C5	F Street / 5th Street SE	36	6	6
C5	F Street / 5th Street SW	36	6	6
C5	F Street / 6th Street NE	36	6	6
C5	F Street / 6th Street NW	36	6	6
C5	F Street / 6th Street SE	36	6	6
C5	F Street / 6th Street SW	36	6	6
C5	F Street / Lincoln NW	12	6	2
C5	F Street / Lincoln SW	12	6	2
C5	Fairway Drive / Glendale Avenue NW	6	1	6
C5	Fairway Drive / Glendale Avenue SW	6	1	6
C5	Fairway Drive / C Street W NE	100	0	6
C5	Fairway Drive / C Street W NW	100	0	6
C5	Fairway Drive / C Street W SE	100	0	6
C5	Fairway Drive / C Street SW	100	0	6
C5	Fairway Drive / A Street W NE	100	0	6
C5	Fairway Drive / A Street W NW	100	0	6
C5	Fairway Drive / A Street W SE	100	0	6
C5	Faiway Drive / A Street W SW	100	0	6
C10	Fermoy Way / Corvey Circle N	36	6	6
C10	Fermoy Way / Corvey Circle NN	36	6	6
C10	Fermoy Way / Corvey Circle S	36	6	6
C10	Fermoy Way / Corvey Circle SS	36	6	6
C10	Fermoy Way / Elk Hills Drive NE	100	0	6
C10	Fermoy Way / Elk Hills Drive SE	100	0	6
C10	Fermoy Way / Jennifer Court N	36	6	6
C10	Fermoy Way / Jennifer Court S	36	6	6
C12	Fermoy Way / Lake Canyon Ave N	36	6	6
C12	Fermoy Way / Lake Canyon Ave S	36	6	6
C12	Fermoy Way / St James Court N	30	5	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C12	Fermoy Way / St James Court S	36	6	6
C10	Fermoy Way / Valentine Court N	36	6	6
C10	Fermoy Way / Valentine Court S	36	6	6
C10	Fermoy Way / Shlley Court SE	100	0	6
C10	Femoy Way / Shelly Court SW	100	0	6
C2	Fernando Way / Germaine NE	36	6	6
C2	Fernando Way / Germaine SE	36	6	6
C6	Finch Drive / Partridge Drive	36	6	6
C2	1st Street / Benner Court NE	36	6	6
C2	1st Street / Benner Court SE	36	6	6
C2	1st Street / Cardoso Drive NE	36	6	6
C2	1st Street / Cardoso Drive SE	36	6	6
C2	1st Street / Carlo Court NW	100	0	6
C2	1st Street / Carlo Court SW	100	0	6
C2	1st Street / Cindy Lane NW	100	0	6
C2	1st Street / Cindy Lane SW	100	0	6
C2	1st Street / Crow Creek Drive N	30	5	6
C2	1st Street / Crow Creek Drive S	42	7	6
C2	1st Street / Downing Drive NE	36	6	6
C2	1st Street / Downing Drive NW	100	0	6
C2	1st Stree / Downing Drive SE	36	6	6
C2	1st Street / Downing Drive SW	100	0	6
C4	1st Street / E Street SE	36	6	6
C4	1st Street / E Street SW	36	6	6
C4	1st Street / F Street NE	36	6	6
C2	1st Street / Kost NE	6	1	6
C2	1st Street / Kost NW	100	0	6
C4	1st Street / New Hope Road NW	36	6	6
C4	1st Street / New Hope Road SW	36	6	6
C4	1st Street / New Hope Road E	36	6	6
C2	1st Street / Pestana Drive NE	36	6	6
C2	1st Street / Pestana Drive SE	36	6	6
C13	Foxtrotter / McKenzie	36	6	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C9	Fulham Court / Maugham Drive NE	100	0	6
C9	Fulham Court / Maugham Drive NW	100	0	6
C4	Fumasi Drive / Oak Wilde Street NE	100	0	2
C4	Fumasi Drive / Oak Wilde Street SW	12	6	2
C4	Fumasi Drive / Oak Wilde Street SE	100	0	2
C4	Fumasi Drive / Sasha Rose NW	100	0	2
C4	Fumasi Drive / Sasha Rose SW	100	0	2
C5	G Street / Church Street NE	6	1	6
C5	G Street / Church Street NW	6	1	6
C5	G Street / Church Street SE	36	6	6
C5	G Street / Church Street SW	36	6	6
C5	G Street / Lincoln Way NW	36	6	6
C5	G Street / Lincoln Way SW	36	6	6
C5	G Street / 6th Street NE	36	6	6
C5	G Street / 6th Street NW	36	6	6
C5	G Street / 5th Street NE	36	6	6
C5	G Street / 5th Street NW	36	6	6
C6	Geranium Circle / Sparrow Drive SSE	100	0	6
C6	Geranium Circle / Sparrow Drive SNE	100	0	6
C6	Geranium Circle / Sparrow Drive NSE	100	0	6
C6	Geranium Circle / Sparrow Drive NNE	100	0	6
C11	Gerling Court / Tierra Creek Drive NW	36	6	6
C11	Gerling Court / Tierra Creek Drive NE	36	6	6
C2	Germaine Drive / Gaylon Way NW	36	6	6
C2	Germaine Drive / Gaylon Way SW	36	6	6
C2	Germaine Drive / Maria Way NW	36	6	6
C2	Germaine Drive / Maria Way NE	36	6	6
C2	Germaine Drive / Maria Way SE	36	6	6
C2	Germaine Drive / Maria Way SW	36	6	6
C9	Gibralter Court / Vauxhall Avenue SE	100	0	6
C9	Gibralter Court / Vauxhall Avenue SW	100	0	6
C5	Glendale Avenue / Casado Drive NE	6	1	6
C5	Glendale Avenue / Casado Drive NW	6	1	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C6	Goshawk Drive / Sparrow Drive SW	36	6	6
C6	Goshawk Drive / Sparrow Drive SE	36	6	6
C9	Griffey Way / Ambrogio Way SE	100	0	6
C9	Griffey Way / Ambrogio Way SW	100	0	6
C9	Griffey Way / Di Maggio Way SE	100	0	6
C9	Griffey Way / Di Maggio Way NE	100	0	6
C9	Griffey Way / Di Maggio Way NW	100	0	6
C6	Grouse Drive / Partridge Drive N	36	6	6
C6	Grouse Drive / Partridge Drive S	36	6	6
C6	Grouse Drive / Pheasant Drive N	36	6	6
C6	Grouse Drive / Pheasant Drive S	36	6	6
C6	Grouse Drive / Quail Hollow Drive E	36	6	6
C6	Grouse Drive / Quail Hollow Drive W	36	6	6
C4	Guild Street / 2nd Street NE	12	6	2
C4	Guild Street / 2nd Street NW	12	6	2
C4	Guild Street / 2nd Street SE	100	0	2
C4	Guild Street / 2nd Street SW	100	0	2
C4	Guild Street / 3rd Street NW	6	1	6
C4	Guild Street / 3rd Street SW	6	1	6
C5	H Street / Almond Court NE	36	6	6
C5	H Street / Almond Court NW	36	6	6
C5	H Street / Church Street NW	36	6	6
C5	H Street / Church Street SW	36	6	6
C5	H Street / Olive Court NE	36	6	6
C5	H Street / Olive Court NW	36	6	6
C11	Halton Court / Parnel Way NW	100	0	6
C11	Halton Court / Parnel Way SW	100	0	6
C3	Hamel Way / Kost Road SW	100	0	6
C3	Hamel Way / Kost Road SE	100	0	6
C3	Hamel Way / McCauley Way NE	100	0	6
C3	Hamel Way / McCauley Way NW	100	0	6
C3	Hamel Way / McCauley Way SW	100	0	6
C3	Hamel Way / McCauley Way SE	100	0	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C3	Hamel Way / Wilder Way NW	100	0	6
C3	Hamel Way / Wilder Way NE	100	0	6
C3	Hamel Way / Wilder Way S	100	0	6
C9	Hamstead Drive / Walworth Drive NE	100	0	6
C9	Hamstead Drive / Walworth Drive NW	100	0	6
C11	Hepworth / Koralla Way E	36	6	6
C11	Hepworth / Koralla Way W	36	6	6
C11	Hickey Way / Bay Shore Drive N	36	6	6
C11	Hickey Way / Bay Shore Drive S	36	6	6
C13	Hiddenwood Drive / Amberhill Avenue N	36	6	6
C13	Hiddenwood Drive / Amberhill Avenue S	36	6	6
C13	Hiddenwood Drive / Elderwood Drive E	36	6	6
C13	Hiddenwood Drive / Elderwood Drive W	36	6	6
C13	Hiddenwood Drive / W. Hill Court E	36	6	6
C13	Hiddenwood Drive / W. Hill Court W	36	6	6
C11	Holmisdale Way / Malton Way S	36	6	6
C11	Holmisdale Way / Malton Way W	36	6	6
C11	Holmisdale Way / Taplin Way N	36	6	6
C11	Holmisdale Way / Taplin Way S	36	6	6
C8	Industrial Court / Industrial Drive N SW	100	0	6
C8	Industrial Court / Industrial Drive S NW	36	6	6
C6	Industrial Drive / Pringle Avenue SE	100	0	6
C6	Industrial Drive / Pringle Avenue SW	36	6	6
C6	Industrial Drive / Elm Avenue NW	100	0	6
C6	Industrial Drive / Elm Avenue NE	100	0	6
C13	Ivywood Drive / Amberhill Avenue	36	6	6
C13	Ivywood Drive / E. Hill Court E	36	6	6
C13	Ivywood Drive / E. Hill Court W	36	6	6
C13	Ivywood Drive / Elderwood Drive E	36	6	6
C13	Ivywood Drive / Elderwood Drive W	36	6	6
C2	Janine Court / Crow Creek Drive E	36	6	6
C2	Janine Court / Crow Creek Drive W	36	6	6
C11	Jordine Way / Presbury Way NE	36	6	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C11	Jordine Way / Presbury Way NW	36	6	6
C11	Jordine Way / Presbury Way SE	36	6	6
C11	Jordine Way / Presbury Way SW	36	6	6
C3	Joy Drive / Kost Road NE	6	1	6
C3	Joy Drive / Kost Road NW	6	1	6
C13	June Court / Park Stream Drive SW	100	0	6
C13	June Court / Park Stream Drive SE	100	0	6
C2	Kandy Street / Tudor Street NE	100	0	6
C2	Kandy Street / Tudor Street SE	100	0	6
C2	Kandy Street / Tudor Street W	100	0	6
C2	Kent Street / Cindy Lane NE	6	1	6
C2	Kent Street / Cindy Lane SW	6	1	6
C9	Killebrew Way / Ambrogio Way NE	100	0	6
C9	Killebrew Way / Ambrogio Way SE	100	0	6
C9	Killebrew Way / Ambrogio Way SW	100	0	6
C9	Killebrew Way / Di Maggio Way NE	100	0	6
C9	Killebrew Way / Di Maggio Way NW	100	0	6
C9	Killebrew Way / Di Maggio Way SW	100	0	6
C2	Kost Road / Raven Brook Drive E	36	6	6
C2	Kost Road / Raven Brook Drive W	36	6	6
C9	La Quita Court / Vauxhall Avenue SE	100	0	6
C9	La Quita Court / Vauxhall Avenue SW	100	0	6
C13	Lake Canyon Avenue / Bay Heights Drive E	12	6	2
C13	Lake Canyon Avenue / Bay Heights Drive W	12	6	2
C13	Lake Canyon Avenue / Beaver Park Way NE	12	6	2
C13	Lake Canyon Avenue / Beaver Park Way NW	12	6	2
C13	Lake Canyon Avenue / Beaver Park Way SE	12	6	2
C13	Lake Canyon Avenue / Beaver Park Way SW	100	0	2
C13	Lake Canyon Avenue / Carillion Avenue NE	30	6	5
C13	Lake Canyon Avenue / Carillion Avenue NW	30	6	5
C13	Lake Canyon Avenue / Carillion Avenue SE	30	6	5
C13	Lake Canyon Avenue / Carillion Avenue SW	30	6	5
C13	Lake Canyon Avenue / Golden Heights Drive NE	30	6	5

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C13	Lake Canyon Avenue / Golden Heights Drive NW	30	6	5
C13	Lake Canyon Avenue / Golden Heights Drive SE	30	6	5
C13	Lake Canyon Avenue / Golden Heights Drive SW	30	6	5
C13	Lake Canyon Avenue / Pinto Trail E	12	6	2
C12	Lake Canyon Avenue / Pinto Trail W	12	6	2
C12	Lake Canyon Avenue / Terra Creek Drive E	36	6	6
C13	Lake Canyon Avenue / Terra Creek Drive W	36	6	6
C13	Lake Canyon Avenue / Thornbridge Drive E	36	6	6
C13	Lake Canyon Avenue / Thornbridge Drive W	36	6	6
C13	Lake Park Avenue	30	6	5
C13	Lake Park Avenue / Amberhill Avenue NE	36	6	6
C13	Lake Park Avenue / Amberhill Avenue NW	36	6	6
C13	Lake Park Avenue / Amberhill Avenue SE	36	6	6
C13	Lake Park Avenue / Amberhill Avenue SW	36	6	6
C13	Lake Park Avenue / Marengo Road N	36	6	6
C13	Lake Park Avenue / Marengo Road S	36	6	6
C13	Lake Park Avenue / Monterey Bay Court E	30	6	5
C13	Lake Park Avenue / Monterey Bay Court W	30	6	5
C13	Lake Park Avenue / Park Terrace Drive NE	36	6	6
C13	Lake Park Avenue / Park Terrace Drive NW	36	6	6
C13	Lake Park Avenue / Park Terrace Drive SE	36	6	6
C13	Lake Park Avenue / Park Terrace Drive SW	36	6	6
C13	Lake Park Avenue / Stormwood Avenue NE	36	6	6
C13	Lake Park Avenue / Stormwood Avenue NW	36	6	6
C13	Lake Park Avenue / Stormwood Avenue SE	36	6	6
C13	Lake Park Avenue / Stormwood Avenue SW	36	6	6
C13	Lake Park Avenue / Warmwood Court E	36	6	6
C13	Lake Park Avenue / Warmwood Court W	36	6	6
C11	Lampard Way / Caversham Way N	12	6	2
C11	Lampard Way / Caversham Way S	12	6	2
C6	Lapwing Lane / Cinnamon Drive E	36	6	6
C6	Lapwing Lane / Cinnamon Drive W	36	6	6
C6	Lapwing Lane / Spoonbill Lane N	36	6	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C6	Lapwing Lane / Spoonbill Lane S	36	6	6
C6	Larkspur Court / Edelweiss Way SW	100	0	6
C6	Larkspur Court / Edelweiss Way NW	100	0	6
C3	Lariat Loop / Lariat Court SW	36	6	6
C3	Lariat Loop / Lariat Court SE	36	6	6
C9	Lauchert Place / Vauxhall Avenue SW	100	0	6
C9	Lauchert Place / Vauxhall Avenue SE	100	0	6
C6	Lavender Court / Edelweiss Way SE	100	0	6
C6	Lavender Court / Edelweiss Way NW	100	0	6
C9	Liebig Court / Wallingotn Drive SE	100	0	6
C9	Liebig Court / Wallington Drive SW	100	0	6
C3	Lincoln / Ranch N	36	6	6
C3	Lincoln / Ranch S	36	6	6
C5	Lincoln Way / Singletree Court N	36	6	6
C5	Lincoln Way / Singletree Court S	36	6	6
C5	Lincoln Way / A Street NE	12	6	2
C5	Lincoln Way / A Street NW	12	6	2
C5	Lincoln Way / A Street SE	12	6	2
C5	Lincoln Way / A Street Standard Intersection Crosswalk N & S	12	6	2
C5	Lincoln Way / A Street SW	12	6	2
C7	Lincoln Way / Amador Avenue Standard Intersection Crosswalk N&S	12	6	2
C5	Lincoln Way / C Street Standard Intersection Crosswalk N & S	100	0	2
C5	Lincoln Way / Chabolla Avenue Standard Crosswalk N & S	12	6	2
C5	Lincoln Way / Chabolla Avenue NE	36	6	6
C5	Lincoln Way / Chabolla Avenue SE	36	6	6
C5	Lincoln Way / D Street Standard Intersection Crosswalk N & S	12	6	2
C5	Lincoln Way / E Street / Caroline Avenue School Crosswalk (Yellow School)	12	6	2
C7	Lincoln Way / Elm Avenue NE	6	1	6
C7	Lincoln Way / Elm Avenue NW	6	1	6
C7	Lincoln Way / Elm Avenue SE	36	6	6
C7	Lincoln Way / Elm Avenue Standard Intersection Crosswalk N & S	36	6	6
C7	Lincoln Way / Elm Avenue SW	36	6	6
C5	Lincoln Way / G Street Standard Intersection Crosswalk N & S	12	6	2

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C3	Lincoln Way / Kost Road Intersection Crosswalk	12	6	2
C3	Lincoln Way / Kost Road NW	100	0	6
C3	Lincoln Way / Kost Road SW	100	0	6
C5	Lincoln Way / Meladee Lane NE	36	6	6
C5	Lincoln Way / Meladee Lane SE	36	6	6
C7	Lincoln Way / Myrtle Avenue School Crosswalk (Yellow School)	36	6	6
C7	Lincoln Way / Single Tree Court NW	100	0	6
C7	Lincoln Way / Single Tree Court SW	100	0	6
C5	Lincoln Way / Southdale Court NE	36	6	6
C5	Lincoln Way / Southdale Court SE	36	6	6
C7	Lincoln Way / Spaans Drive Crosswalk N & S (Mid-Block)	12	6	2
C7	Lincoln Way / Terrace Lane NE	100	0	6
C7	Lincoln Way / Terrace Lane SE	100	0	6
C7	Lincoln Way / Wendy Hope Drive NE	100	0	6
C7	Lincoln Way / Wendy Hope Drive SE	100	0	6
C7	Lois Avenue / Gary Avenue	36	6	6
C6	Lorna Way / Clover Court SE	36	6	6
C6	Lorna Way / Clover Court SW	36	6	6
C6	Lorna Way / Clover Court NE	36	6	6
C6	Lorna Way / Fern Court SE	36	6	6
C6	Lorna Way / Fern Court SW	36	6	6
C9	Lyonia Drive / Wicker Way N	36	6	6
C9	Lyonia Drive / Wicker Way S	36	6	6
C6	Mallard Drive / Grouse Drive N	36	6	6
C6	Mallard Drive / Grouse Drive S	36	6	6
C6	Mallard Drive / Sandpiper Drive E	36	6	6
C6	Mallard Drive / Sandpiper Drive W	36	6	6
C6	Mallard Drive / Shelduck Lane E	36	6	6
C6	Mallard Drive / Shelduck Lane W	36	6	6
C11	Malton Way / Duncraig Way E	36	6	6
C11	Malton Way / Duncraig Way N	36	6	6
C9	Marengo Road / Vauxhall Avenue NW	100	0	6
C9	Marengo Road / Vauxhall Avenue SW	100	0	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C9	Marengo Road / Maugham Drive SW	100	0	6
C9	Marengo Road / Maugham Drive NW	100	0	6
C11	Marengo Road / Walnut Avenue NW	36	6	6
C11	Marengo Road / Walnut Avenue SE	36	6	6
C9	Marichal Way / Griffey Way NE	100	0	6
C9	Marichal Way / Griffey Way SE	100	0	6
C9	Marichal Way / Griffey Way NW	100	0	6
C9	Marichal Way / Killebrew Way NE	100	0	6
C9	Marichal Way / Killebrew Way NW	100	0	6
C9	Marichal Way / Killebrew Way SE	100	0	6
C9	Marichal Way / Killebrew Way SW	100	0	6
C13	Marine Bay Drive / Breakers Drive NE	36	6	6
C13	Marine Bay Drive / Breakers Drive NW	36	6	6
C13	Marine Bay Drive / Breakers Drive SE	36	6	6
C13	Marine Bay Drive / Breakers Drive SW	36	6	6
C9	Maugham Court / Maugham Drive NE	100	0	6
C9	Maugham Court / Muagham Drive NW	100	0	6
C9	Maugham Court / Portland Lane NE	100	0	6
C9	Maugham Court / Portland Lane NW	100	0	6
C4	McTucker Drive / Turnace Court NW	30	6	5
C4	McTucker Drive / Turnace Court SW	30	6	5
C9	McAlta Court / Hamstead Drive NE	100	0	6
C9	McAlta Court / Hamstead Drive SE	100	0	6
C3	McCauley Way / Wilder Way SE	100	0	6
C3	McCauley Way / Wilder Way NE	100	0	6
C3	McCauley Way / Wilder Way NW	100	0	6
C3	McCauley Way / Wise Way SE	100	0	6
C3	McCauley Way / Wise Way SW	100	0	6
C3	McCauley Way / Wise Way N	100	0	6
C9	McEnerney Court / Tottenham Drive NE	100	0	6
C9	McEnerney Court / Tottenham Drive SE	100	0	6
C6	McFarland Street / West Elm Avenue SW	36	6	6
C6	McFarland Street / West Elm Avenue SE	6	1	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C2	Meadowview Drive / Carlo Court NE	100	0	6
C2	Meadowview Drive / Carlo Court NW	100	0	6
C2	Meadowview Drive / Carlo Court SE	100	0	6
C2	Meadowview Drive / Carlo Court SW	100	0	6
C2	Meadowview Drive / Creekside Way NW	6	1	6
C2	Meadowview Drive / Creekside Way SW	6	1	6
C2	Meadowview Drive / Dover Drive NW	6	1	6
C2	Meadowview Drive / Dover Drive SW	6	1	6
C2	Meadowview Drive / Kost NE	100	0	5
C2	Meadowview Drive / Kost NW	100	0	5
C2	Meadowview Drive / Cindy Lane SE	6	1	6
C2	Meadowview Drive / Cindy Lane SW	6	1	6
C5	Meladee Lane / Casado Drive SE	100	0	5
C5	Meladee Lane / Casado Drive SW	100	0	5
C5	Meladee Lane / Casado Drive S	30	6	5
C5	Meladee Lane / Glendale Avenue SE	100	0	6
C5	Meladee Lane / Glendale Avenue SW	100	0	6
C5	Meladee Lane / Glendale Avenue NE	100	0	6
C5	Meladee Lane / Glendale Avenue NW	100	0	6
C7	Mildred Avenue / Elm Avenue SE	100	0	6
C7	Mildred Avenue / Elm Avenue SW	100	0	6
C13	Monterey Bay Court / Carpinteria Drive N	30	6	5
C13	Monterey Bay Court / Carpinteria Drive S	30	6	5
C11	Moose Creek Way / Port Ashton Court E	36	6	6
C11	Moose Creek Way / Port Ashton Court W	36	6	6
C13	Morgans Ranch Circle N / Pinto Trail Drive NE	36	6	6
C13	Morgans Ranch Circle N / Pinto Trail Drive SE	36	6	6
C13	Morgans Ranch Circle S / Pinto Trail Drive SE	36	6	6
C13	Morgans Ranch Circle S / Pinto Trail Drive NE	36	6	6
C6	Myrtle Avnue / Oak Avenue N	100	0	3
C6	Myrtle Avenue / Oak Avenue S	100	0	3
C6	Myrtle Avenue / Oak Avenue W	36	6	6
C7	Myrtle Avenue / Lincoln Way SW	12	6	2

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C7	Myrtle Avenue / Lincoln Way NW	12	6	2
C7	Myrtle Avenue / Lois Avenue NE	36	6	6
C7	Myrtle Avenue / Lois Avenue NW	36	6	6
C11	Neville Way / Walnut Avenue E	36	6	6
C11	Neville Way / Walnut Avenue W	36	6	6
C2	New Hope Road / Eric Circle East South West	12	6	2
C2	New Hope Road / Eric Circle West South East	36	6	6
C2	New Hope Road / Eric Circle West South West	36	6	6
C2	New Hope Road / Silverado Way NE	36	6	6
C2	New Hope Road / Silverado Way NW	36	6	6
C2	New Hope Road / Spur Way NE	5	1	5
C2	New Hope Road / Spur Way NW	30	6	5
C2	New Hope Road / Village Run NE	36	6	6
C2	New Hope Road / Village Run NW	36	6	6
C2	New Hope Road / McTucker Drive NE	36	6	6
C2	New Hope Road / McTucker Drive NW	36	6	6
C11	Norbury Way / Presbury Way N	36	6	6
C11	Norbury Way / Presbury Way S	36	6	6
C11	Norbury Way / Ranford Court N	36	6	6
C11	Norbury Way / Ranford Court S	36	6	6
C4	Oak Avenue / A Street E	36	6	6
C4	Oak Avenue / A Street W	36	6	6
C4	Oak Avenue / A Street S	100	0	6
C4	Oak Wilde Street / Danny Drive SE	100	0	2
C4	Oak Wilde Street / Danny Drive SW	100	0	2
C4	Oak Wilde Street / Jonathon Court NE	100	0	6
C4	Oak Wilde Street / Jonathon Court NW	100	0	6
C4	Oak Wilde Street / Justin Court NE	100	0	6
C4	Oak Wilde Street / Justin Court NW	100	0	6
C4	Oak Wilde Street / Michelle Court NE	100	0	6
C4	Oak Wilde Street / Michelle Court NW	100	0	6
C4	Oak Wilde Street / South Emerald Oak Drive NE	100	0	6
C4	Oak Wilde Street / South Emerald Oak Drive NW	100	0	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C4	Oak Wilde Street / South Emerald Oak Drive SW	100	0	6
C4	Oak Wilde Street / Toni Court NE	12	6	2
C4	Oak Wilde Street / Toni Court NW	12	6	2
C6	Oberlin Way / Lorna Way NW	36	6	6
C6	Oberlin Way / Lorna Way SW	36	6	6
C6	Oberlin Way / Rossi Drive NW	6	1	6
C6	Oberlin Way / Rossi Drive SW	6	1	6
C6	Oberlin Way / Trudy Way NE	6	1	6
C6	Oberlin Way / Trudy Way SE	6	1	6
C6	Oberlin Way / Wildflower Drive NW	6	1	6
C6	Oberlin Way / Wildflower Drive SW	6	1	6
C13	Oldenburg Way / Pinto Trail Drive NW	36	6	6
C13	Oldenburg Way / Pinto Trail Drive NE	36	6	6
C13	Oldenburg Way / Pinto Trail Drive SW	36	6	6
C13	Oldenburg Way / Pinto Trail Drive SE	36	6	6
C11	Olive Canyon Drive / Cedar Canyon Circle E	36	6	6
C11	Olive Canyon Drive / Cedar Canyon Circle W	36	6	6
C11	Olive Canyon Drive / Golden Heights Drive E	30	6	5
C11	Olive Canyon Drive / Golden Heights Drive W	30	6	5
C9	Paddington Circle / Vauxhall Avenue ENW	100	0	6
C9	Paddington Circle / Vauxhall Avenue ENE	100	0	6
C9	Paddington Circle / Vauxhall Avenue WNE	100	0	6
C9	Paddington Circle / Vauxhall Avenue WNW	100	0	6
C7	Palin Avenue / Gary Avenue NE	36	6	6
C7	Palin Avenue / Gary Avenue SE	36	6	6
C7	Palin Avenue / Myrtle Avenue NE	36	6	6
C7	Palin Avenue / Myrtle Avenue NW	100	0	6
C7	Palin Avenue / Myrtle Avenue SE	36	6	6
C7	Palin Avenue / Myrtle Avenue SW	36	6	6
C7	Palin Avenue / Simons Street SW	100	0	6
C7	Palin Avenue / Simons Street SE	100	0	6
C7	Palin Avenue / Simons Street NW	100	0	6
C7	Palin Avenue / Simons street NE	100	0	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C7	Palin Avenue / A Street E	36	6	6
C7	Palin Avenue / A Street W	36	6	6
C13	Park Heights Drive / Biloxi Park Court E	36	6	6
C13	Park Heights Drive / Biloxi Park Court W	36	6	6
C13	Park Heights Drive / Park Stream Drive NE	36	6	6
C13	Park Heights Drive / Park Stream Drive NW	36	6	6
C13	Park Heights Drive / Park Stream Drive SE	36	6	6
C13	Park Heights Drive / Park Stream Drive SW	36	6	6
C13	Park Heights Drive / Park Valley Court E	36	6	6
C13	Park Heights Drive / Park Valley Court W	36	6	6
C13	Park Heights Drive / Park Valley Way E	36	6	6
C13	Park Heights Drive / Park Valley Way W	36	6	6
C13	Park Heights Drive / Sidell Park Court E	36	6	6
C13	Park Heights Drive / Sidell Park Court W	36	6	6
C13	Park Stream Drive / Stormwood Avenue N	36	6	6
C13	Park Stream Drive / Stormwood Avenue S	36	6	6
C13	Park Terrace Drive / Park Stream Drive NE	36	6	6
C13	Park Terrace Drive / Park Stream Drive NW	36	6	6
C13	Park Terrace Drive / Park Stream Drive SE	36	6	6
C13	Park Terrace Drive / Park Stream Drive SW	36	6	6
C11	Park Terrace Drive / Steele Way NE	36	6	6
C11	Park Terrace Drive / Steele Way SE	36	6	6
C11	Park Terrace Drive / Walnut Avenue NE	36	6	6
C11	Park Terrace Drive / Walnut Avenue SW	36	6	6
C13	Park Valley Way / Park Heights Drive SE	36	6	6
C13	Park Valley Way / Park Heights Drive SW	36	6	6
C13	Park Valley Way / Park Stream Court NW	100	0	6
C13	Park Valley Way / Park Stream Drive NE	100	0	6
C11	Parnel Way / Beeler Way NE	36	6	6
C11	Parnel Way / Beeler Way SW	36	6	6
C11	Parnel Way / Halton Court N	36	6	6
C11	Parnel Way / Halton Court S	36	6	6
C11	Parnel Way / Norbury Way N	36	6	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C11	Parnel Way / Norbury Way S	36	6	6
C2	Pestana Drive / Fernando Way NE	36	6	6
C2	Pestana Drive / Fernando Way NW	36	6	6
C2	Pestana Drive / Gaylon Way NW	36	6	6
C2	Pestana Drive / Gaylon Way SE	36	6	6
C2	Pestana Drive / Maria Way NE	36	6	6
C2	Pestana Drive / Maria Way NW	36	6	6
C2	Pestana Drive / Maria Way SE	36	6	6
C2	Pestana Drive / Maria Way SW	36	6	6
C6	Pheasant Drive / Finch Drive N	36	6	6
C6	Pheasant Drive / Finch Drive S	36	6	6
C6	Pheasant Drive / Robin Lane E	36	6	6
C6	Pheasant Drive / Robin Lane W	36	6	6
C11	Piermont Way / Action Way N	36	6	6
C11	Piermont Way / Action Way S	36	6	6
C13	Pinto Trail / Foxtrotter Way E	36	6	6
C13	Pinto Trail / Foxtrotter Way W	36	6	6
C13	Pinto Trail / Hanoverian Circle N	36	6	6
C13	Pinto Trail / Hanoverian Circle NN	36	6	6
C13	Pinto Trail / Hanoverian Circle S	36	6	6
C13	Pinto Trail / Hanoverian Circle SS	36	6	6
C13	Pinto Trail / Holsteiner Court N	36	6	6
C13	Pinto Trail / Holsteiner Court S	36	6	6
C13	Pinto Trail / Morgans Ranch Circle N	36	6	6
C13	Pinto Trail / Morgans Ranch Circle NN	36	6	6
C13	Pinto Trail / Morgans Ranch Circle S	36	6	6
C13	Pinto Trail / Oldenburg Way NE	36	6	6
C13	Pinto Trail / Oldenburg Way NW	36	6	6
C13	Pinto Trail / Oldenburg Way SE	36	6	6
C13	Pinto Trail / Oldenburg Way SW	36	6	6
C13	Pinto Trail / Trakhaner Court N	36	6	6
C13	Pinto Trail / Trakhaner Court S	36	6	6
C6	Poplar Street / Oak Avenue N	36	6	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C6	Poplar Street / Oak Avenue S	36	6	6
C11	Poppy Court / Vintage Oak Avenue NE	36	6	6
C11	Poppy Court / Vintage Oak Avenue SE	36	6	6
C9	Portland Lane / Wallingotn Drive NE	100	0	6
C9	Portland Lane / Wallingotn Drive NW	100	0	6
C8	Pringle Avenue / Lincoln Way NW	100	0	6
C8	Pringle Avenue / Linclon Way SE	100	0	6
C8	Pringle Avenue / Lincoln Way SW	100	0	6
C6	Quial Hollow Drive / Emerald Oak Drive N	36	6	6
C6	Quial Hollow Drive / Emerald Oak Drive S	36	6	6
C9	Rachel Drive / Cobble Hill Way N	36	6	6
C9	Rachel Drive / Cobble Hill Way S	36	6	6
C9	Rachel Drive / Emerald Vista Drive	30	6	5
C4	Ramon Drive / Emerald Oak Drive N	36	6	6
C4	Ramon Drive / Emerald Oak Drive S	36	6	6
C3	Ranch Road / Bernal Road NE	36	6	6
C3	Ranch Road / Bernal Road NW	36	6	6
C3	Ranch Road / Bonanza Drive SE	36	6	6
C3	Ranch Road / Bonanza Drive SW	36	6	6
C3	Ranch Road / Bridle Path SW	36	6	6
C3	Ranch Road / Bridle Path SE	36	6	6
C3	Ranch Road / Larait Loop West NW	36	6	6
C3	Ranch Road / Larait Loop East NW	36	6	6
C3	Ranch Road / Larait Loop East NE	36	6	6
C3	Ranch Road / Larait Loop West NE	36	6	6
C3	Ranch Road / Lincoln Way NE	36	6	6
C3	Ranch Road / Lincoln Way SE	36	6	6
C3	Ranch Road / Tradepost SE	36	6	6
C3	Ranch Road / Tradepost SW	36	6	6
C4	Range Way / Plains Court NE	36	6	6
C4	Range Way / Plains Court SE	36	6	6
C4	Range Way / Rio Mesa Court NE	36	6	6
C4	Range Way / Rio Mesa Court SE	36	6	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C4	Range Way / Rio Mesa NW	36	6	6
C4	Range Way / Rio Mesa SW	36	6	6
C4	Range Way / West C Street SE	36	6	6
C4	Range Way / West C Street SW	36	6	6
C2	Raven Brook Drive / Kost Road NE	100	0	6
C2	Raven Brook Drive / Kost Road NW	100	0	6
C2	Raven Brook Drive / Crow Creek SE	36	6	6
C2	Raven Brook Drive / Crow Creek SW	36	6	6
C2	Raven Brook Drive / Crow Creek N	36	6	6
C4	Rio Mesa Way / Driscol Drive SE	36	6	6
C4	Rio Mesa Way / Driscol Drive SW	36	6	6
C4	Rio Mesa Way / Driscol Drive N	36	6	6
C4	Rio Mesa Way / Sasha Rose SE	36	6	6
C4	Rio Mesa Way / West C Street NE	100	0	6
C4	Rio Mesa Way / West C Street NW	100	0	6
C4	Rio Mesa Way / West C Street SE	100	0	6
C4	Rio Mesa Way / West C Street SW	100	0	6
C4	Rio Mesa Way / Wristen Way NE	36	6	6
C4	Rio Mesa Way / Wristen Way SE	36	6	6
C4	Rio Mesa Way / Wristen Way SW	36	6	6
C9	Ripken Avenue / Ambrogio Way NE	100	0	6
C9	Ripken Avenue / Ambrogio Way NW	100	0	6
C6	Robin Lane / Robin Court N	36	6	6
C6	Robin Lane / Robin Court S	36	6	6
C11	Rossburn Way / Cobden Way NE	36	6	6
C11	Rossburn Way / Cobden Way SW	36	6	6
C6	Rossi Drive / Oberlin Way N	36	6	6
C6	Rossi Drive / Oberlin Way S	36	6	6
C6	Rossi Drive / Sunshine Drive NE	36	6	6
C6	Rossi Drive / Sunshine Drive NW	36	6	6
C6	Rossi Drive / Sunshine Drive SE	36	6	6
C6	Rossi Drive / Sunshine Drive SW	36	6	6
C9	Roundstone Drive / Trafalgar Circle E	36	6	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C9	Roundstone Drive / Trafalgar Circle W	36	6	6
C4	Rowland Court / C Street NW	36	6	6
C4	Rowland Court / C Street NE	36	6	6
C6	Sandpiper Drive / Grouse Drive N	36	6	6
C6	Sandpiper Drive / Grouse Drive S	36	6	6
C13	Saunders Court / Park Stream Drive SW	36	6	6
C13	Saunders Court / Park Stream Drive SE	36	6	6
C9	Seaver Court / Killebrew Way SW	100	0	6
C9	Seaver Court / Killebrew Way NW	100	0	6
C11	Shalford Way / Embleton Court	36	6	6
C11	Shalford Way / Neville Way E	36	6	6
C11	Shalford Way / Neville Way W	36	6	6
C6	Shelduck Lane / Wren Drive N	36	6	6
C6	Shelduck Lane / Wren Drive S	36	6	6
C9	Sherborne Court / Vauxhall Avenue SE	100	0	6
C9	Sherborne Court / Vauxhall Avenue SW	100	0	6
C6	Simons Street / Crescent Drive NE	36	6	6
C6	Simons Street / Crescent Drive NW	36	6	6
C6	Simons Street / Oak Avenue N	100	0	6
C6	Simons Street / Oak Avenue S	100	0	6
C6	Simons Street / Oak Avenue W	100	0	6
C7	Simons Street / Palin Drive NE	36	6	6
C7	Simons Street / Palin Drive NW	36	6	6
C7	Simons Street / Palin Drive SE	36	6	6
C7	Simons Street / Palin Drive SW	36	6	6
C7	Simons Street / Lincoln Way NW	100	0	6
C7	Simons Street / Lincoln Way SW	100	0	6
C7	Simons Street / Mildred Avenue NE	36	6	6
C7	Simons Street / Mildred Avenue NW	36	6	6
C13	Snow Lily Avenue / Lake Canyon Avenue E	36	6	6
C13	Snow Lily Avenue / Lake Canyon Avenue W	36	6	6
C13	Snow Lily Avenue / Wild Poppy Court E	36	6	6
C13	Snow Lily Avenue / Wild Poppy Court W	36	6	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C13	Snow Lily Avenue / Woodflower Court E	36	6	6
C13	Snow Lily Avenue / Woodflower Court W	36	6	6
C4	South Emerald Oak Drive / Big Jake Way NE	100	0	6
C4	South Emerald Oak Drive / Big Jake Way SE	100	0	6
C4	South Emerald Oak Drive / West C Street NW	100	0	5
C4	South Emerald Oak Drive / West C Street NE	100	0	5
C4	South Emerald Oak Drive / West C Street SE	100	0	6
C5	Southdale Court / Meladee Lane SE	6	1	6
C5	Southdale Court / Meladee Lane SW	6	1	6
C7	Spaans Drive / Lincoln Way NW	36	6	6
C7	Spaans Drive / Lincoln Way SW	36	6	6
	Spaans Drive / Lincoln Way NE	100	0	6
C4	Sparrow Drive / Sterling Grove N	36	6	6
C4	Sparrow Drive / Sterling Grove S	36	6	6
C6	Sparrow Drive / Mallard Drive N	36	6	6
C6	Sparrow Drive / Mallard Drive S	36	6	6
C6	Sparrow Drive / Quail Hollow Drive NE	36	6	6
C6	Sparrow Drive / Quail Hollow Drive NW	36	6	6
C6	Sparrow Drive / Quail Hollow Drive SE	36	6	6
C6	Sparrow Drive / Quail Hollow Drive SW	36	6	6
C6	Sparrow Drive / Wren Drive N	36	6	6
C6	Sparrow Drive / Wren Drive S	36	6	6
C6	Spoonbill Lane / Lapwing Lane N	36	6	6
C6	Spoonbill Lane / Lapwing Lane S	36	6	6
C6	Spruce Avenue / A Street E	36	6	6
C6	Spruce Avenue / A Street W	36	6	6
C4	Spur Way / Silverado Way NW	36	6	6
C4	Spur Way / Silverado Way SW	36	6	6
C3	Stampede Trail / Bonanza Drive NW	36	6	6
C3	Stampede Trail / Bonanza Drive SE	36	6	6
C3	Stampede Trail / Tradepost Trail NE	100	0	6
C3	Stampede Trail / Tradepost Trail NW	100	0	6
C3	Stampede Trail / Tradepost Trail SW	100	0	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C13	Starbrook Drive / Hickey Way N	36	6	6
C13	Starbrook Drive / Hickey Way S	36	6	6
C11	Steele Way / Shalford Way E	36	6	6
C11	Steele Way / Shalford Way W	36	6	6
C3	Stefan Court / Wilder Way S	100	0	6
C3	Stefan Court / Wilder Way NW	100	0	6
C3	Stefan Court / Wilder Way NE	100	0	6
C4	Sterling Grove / Silver Aspen Court E	36	6	6
C4	Sterling Grove / Silver Aspen Court NW	36	6	6
C4	Sterling Grove / Silver Aspen Court W	36	6	6
C4	Sterling Grove / Silver Cypress Court E	36	6	6
C4	Sterling Grove / Silver Cypress Court NW	36	6	6
C4	Sterling Grove / Silver Cypress Court W	36	6	6
C4	Sterling Grove / Silver Pine Court E	36	6	6
C4	Sterling Grove / Silver Pine Court NW	36	6	6
C4	Sterling Grove / Silver Pine Court W	36	6	6
C4	Sterling Grove / Silver Spruce Court E	36	6	6
C4	Sterling Grove / Silver Spruce Court W	36	6	6
C4	Sterling Grove / Silver Willow Court E	36	6	6
C4	Sterling Grove / Silver Willow Court W	36	6	6
C4	Sterling Grove / Spoonbill Lane E	36	6	6
C4	Sterling Grove / Spoonbill Lane W	36	6	6
C4	Sterling Grove / Sterling Oak Drive NE	36	6	6
C4	Sterling Grove / Sterling Oak Drive NW	36	6	6
C4	Sterling Grove / Sterling Oak Drive SE	36	6	6
C4	Sterling Grove / Sterling Oak Drive SW	36	6	6
C9	Stoneygate Drive / Roundstone Drive N	36	6	6
C9	Stoneygate Drive / Roundstone Drive S	36	6	6
C13	Stormwood Avenue / Bentwood Drive	36	6	6
C13	Stormwood Avenue / Dawnwood Drive N	36	6	6
C13	Stormwood Avenue / Dawnwood Drive S	36	6	6
C13	Stormwood Avenue / Hiddenwood Drive N	36	6	6
C13	Stormwood Avenue / Hiddenwood Drive S	36	6	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Gnd	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C13	Stormwood Avenue / Ivywood Drive	36	6	6
C11	Strathaven Way / Rossburn Way N	36	6	6
C11	Strathaven Way / Rossburn Way S	36	6	6
C9	Sugarwood Court / Vintage Oak Avenue SE	36	6	6
C9	Sugarwood Court / Vintage Oak Avenue SW	36	6	6
C9	Summit Lakes / Almanor Way N	36	6	6
C9	Summit Lakes / Almanor Way S	36	6	6
C6	Sunshine Drive / Jennifer Way E	36	6	6
C6	Sunshine Drive / Jennifer Way W	36	6	6
C6	Sunshine Drive / Lorna Way NE	36	6	6
C6	Sunshine Drive / Lorna Way SE	36	6	6
C6	Sunshine Drive / Oberlin Way NE	36	6	6
C6	Sunshine Drive / Wildflower Drive NE	36	6	6
C6	Sunshine Drive / Wildflower Drive SE	36	6	6
C6	Sunshine Drive / Wildflower Drive SW	36	6	6
C9	Taggart Court / Portland Lane NW	100	0	6
C9	Taggart Court / Portland Lane SW	100	0	6
C11	Taplin Way / Park Terrace Drive NW	12	6	2
C11	Taplin Way / Park Terrace Drive SW	36	6	6
C6	Teal Lane / Robin Lane NE	36	6	6
C6	Teal Lane / Robin Lane SE	36	6	6
C7	Terrace Lane / Camellia Way NW	6	1	6
C7	Terrace Lane / Camellia Way SW	6	1	6
C7	Terrace Lane / Camellia Way SE	6	1	6
C7	Terrace Lane / Park Avenue NE	6	1	6
C7	Terrace Lane / Park Avenue NW	6	1	6
C7	Terrace Lane / Park Avenue SE	36	6	6
C7	Terrace Lane / Park Avenue SW	36	6	6
C13	Thornbridge Drive / Lake Park Avenue E	42	7	6
C13	Thornbridge Drive / Lake Park Avenue W	42	7	6
C13	Thornbridge Drive / Scarletwood Court N	42	7	6
C13	Thornbridge Drive / Scarletwood Court S	42	7	6
C13	Thornbridge Drive / Snow Lily Avenue NE	42	7	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C13	Thornbridge Drive / Snow Lily Avenue NW	42	7	6
C13	Thornbridge Drive / Snow Lily Avenue SE	42	7	6
C13	Thornbridge Drive / Snow Lily Avenue SW	42	7	6
C13	Thornbridge Drive / Wildginger Court N	42	7	6
C13	Thornbridge Drive / Wildginger Court S	42	7	6
C11	Tierra Creek Drive / Courtenay Court N	36	6	6
C11	Tierra Creek Drive / Courtenay Court S	42	7	6
C11	Tierra Creek Drive / Starbrook Drive	42	7	6
C11	Tierra Creek Drive / Starbrook Drive	42	7	6
C11	Tierra Creek Drive / Starbrook Drive E	42	7	6
C11	Tierra Creek Drive / Starbrook Drive W	42	7	6
C11	Tierra Creek Drive / Wild Brook Court N	42	7	6
C11	Tierra Creek Drive / Wild Brook Court S	42	7	6
C9	Tottenham Court / Maugham Drive NW	100	0	6
C9	Tottenham Court / Maugham Drive NE	100	0	6
C9	Tottenham Drive / Maugham Drive SE	100	0	6
C9	Tottenham Drive / Maugham Drive SW	100	0	6
C9	Trafalgar Circle / Vauxhall Avenue East NE	42	7	6
C9	Trafalgar Circle / Vauxhall Avenue East NW	42	7	6
C9	Trafalgar Circle / Vauxhall Avenue East SE	42	7	6
C9	Trafalgar Circle / Vauxhall Avenue East SW	42	7	6
C9	Trafalgar Circle / Vauxhall Avenue West NE	42	7	6
C9	Trafalgar Circle / Vauxhall Avenue West NW	42	7	6
C9	Trafalgar Circle / Vauxhall Avenue West SE	42	7	6
C9	Trafalgar Circle / Vauxhall Avenue West SW	42	7	6
C9	Trammel Way / Manton Court N	42	7	6
C9	Trammel Way / Manton Court S	42	7	6
C9	Trammel Way / Stenton Way E	42	7	6
C9	Trammel Way / Stenton Way W	42	7	6
C6	Trent Drive / Oberlin Drive	42	7	6
C6	Trudy Way / McFarland Street NW	100	0	6
C6	Trudy Way / McFarland Street SW	100	0	6
C2	Tudor Street / Cindy Lane NE	6	1	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C2	Tudor Street / Cindy Lane SE	6	1	6
C2	Tudor Street / Cindy Lane W	100	0	6
C2	Tudor Street / Dover Drive NE	100	0	6
C2	Tudor Street / Dover Drive SE	100	0	6
C2	Tudor Street / Dover Drive W	100	0	6
C2	Tudor Street / Downing NE	100	0	6
C2	Tudor Street / Downing NW	100	0	6
C2	Tudor Street / Downing SE	100	0	6
C2	Tudor Street / Downing SW	100	0	6
C2	Tudor Street / Kost NE	100	0	6
C2	Tudor Street / Kost NW	100	0	6
C2	Tudor Street / Terry Street NW	100	0	6
C2	Tudor Street / Terry Street SW	100	0	6
C2	Tudor Street / Terry Street E	100	0	6
C13	Twin Cities Road / Park Terrace Drive SE	36	6	6
C13	Twin Cities Road / Park Terrace Drive SW	36	6	6
C13	Twin Cities Road / Carillion Boulevard SW	100	0	6
C13	Twin Cities Road / Carillion Boulevard SE	36	6	6
C13	Twin Cities Road / Foxtrotter Way SE	36	6	6
C13	Twin Cities Road / Foxtrotter Way SW	36	6	6
C12	Twin Cities Road / Fermoy Way SW	100	0	6
C12	Twin Cities Road / Fermoy Way SE	36	6	6
C12	Twin Cities Road / East Stockton Boulevard SE	18	3	6
C12	Twin Cities Road / East Stockton Boulevard NE	18	3	6
C12	Twin Cities Road / East Stockton Bolouverd NW	18	3	6
C12	Twin Cities Road / East Stockton Boulevard SW	18	3	6
C11	Twin Hills Drive / Beaver Way	42	7	6
C9	Vauxhall Avenue / Fran Court E	42	7	6
C9	Vauxhall Avenue / Fran Court W	42	7	6
C9	Vauxhall Avenue / Speakers Court E	42	7	6
C9	Vauxhall Avenue / Speakers Court W	42	7	6
C6	Victorian Park Drive / 4th Street E	18	6	3
C6	Victorian Park Drive / 4th Street W	18	6	3

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C6	Victorian Park Drive / Alice Rae Circle E	18	6	3
C6	Victorian Park Drive / Alice Rae Circle EE	18	6	3
C6	Victorian Park Drive / Alice Rae Circle W	36	6	6
C6	Victorian Park Drive / Alice Rae Circle WW	36	6	6
C6	Victorian Park Drive / Oak Avenue NE	18	6	3
C6	Victorian Park Drive / Oak Avenue SE	18	6	3
C6	Victorian Park Drive / Spruce Avenue E	18	6	3
C6	Victorian Park Drive / Spruce Avenue W	18	6	3
C11	Vintage Oak Avenue / Benteen Way E	42	7	6
C11	Vintage Oak Avenue / Benteen Way W	42	7	6
C9	Vintage Oak Avenue / Sugarwood Court NW	42	7	6
C9	Vintage Oak Avenue / Sugarwood Court SE	42	7	6
C9	Vintage Oak Avenue / Cedar Flat Way NE	14	7	2
C9	Vintage Oak Avenue / Cedar Flat Way NW	14	7	2
C9	Vintage Oak Avenue / Cedar Flat Way SE	14	7	2
C9	Vintage Oak Avenue / Cedar Flat Way SW	14	7	2
C9	Vintage Oak Avenue / Claybury Court NE	42	7	6
C9	Vintage Oak Avenue / Claybury Court S	42	7	6
C9	Vintage Oak Avenue / Elk Hills Drive	42	7	6
C9	Vintage Oak Avenue / Rachel Drive NE	42	7	6
C9	Vintage Oak Avenue / Rachel Drive NW	100	0	6
C9	Vintage Oak Avenue / Rachel Drive SE	100	0	6
C9	Vintage Oak Avenue / Rachel Drive SW	100	0	6
C9	Vintage Oak Avenue / Summit Lakes Way NE	100	0	2
C9	Vintage Oak Avenue / Summit Lakes Way NW	100	0	2
C9	Vintage Oak Avenue / Summit Lakes Way SE	100	0	2
C9	Vintage Oak Avenue / Summit Lakes Way SW	100	0	2
C9	Vintage Oak Avenue / Vanduzen Court E	100	0	6
C9	Vintage Oak Avenue / Vanduzen Court W	100	0	6
C4	Wagon Way / Branding Iron Way NE	36	6	6
C4	Wagon Way / Branding Iron Way SE	36	6	6
C4	Wagon Way / Chaps Court NE	36	6	6
C4	Wagon Way / Chaps Court SE	36	6	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C4	Wagon Way / Saddle Court NW	36	6	6
C4	Wagon Way / Saddle Court SW	36	6	6
C4	Wagon Way / Stirrup Court NW	36	6	6
C4	Wagon Way / Stirrup Court SW	36	6	6
C9	Wallington Drive / Hamstead Drive NW	100	0	6
C9	Wallington Drive / Hamstead Drive SE	100	0	6
C4	Walnut Avenue / Carillion Boulevard NE	100	0	5
C11	Walnut Avenue / Carillion Boulevard NW	100	0	5
C11	Walnut Avenue / Carillion Boulevard SE	100	0	5
C11	Walnut Avenue / Carillion Boulevard SW	100	0	5
C11	Walnut Avenue / Elk Hills Drive E	100	0	2
C11	Walnut Avenue / Elk Hills Drive W	100	0	2
C11	Walnut Avenue / Vintage Oak Way E	100	0	6
C11	Walnut Avenue / Vintage Oak Way N	100	0	6
C11	Walnut Avenue / Vintage Oak Way S	100	0	6
C11	Walnut Avenue / Vintage Oak Way W	100	0	6
C9	Walworth Drive / Wallington Drive NE	100	0	6
C9	Walworth Drive / Wallington Drive SE	100	0	6
C9	Walworth Drive / Wallington Drive SW	100	0	6
C9	Waterloo Court / Maugham Drive NE	100	0	6
C9	Waterloo Court / Maugham Drive NW	100	0	6
C7	Wendy Hope Drive / Beno Court NW	6	1	6
C7	Wendy Hope Drive / Beno Court NE	6	1	6
C7	Wendy Hope Drive / Camellia Way NW	6	1	6
C7	Wendy Hope Drive / Camellia Way SW	6	1	6
C7	Wendy Hope Drive / Curtis Court NE	6	1	6
C7	Wendy Hope Drive / Curtis Court NW	6	1	6
C4	West A Street / Fumasi Drive SE	36	6	6
C4	West A Street / Fumasi Drive SW	36	6	6
C4	West A Street / Silver Aspen Court	100	0	6
C4	West A Street / Silver Cypress Court	100	0	2
C4	West A Street / Silver Pine Court	100	0	6
C4	West A Street / Silver Spruce Court	100	0	6
C4	West A Street / Silver Willow Court	100	0	2

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C4	West A Street / Sparrow Drive E	100	0	2
C4	West A Street / Sparrow Drive W	100	0	2
C4	West A Street / Emerald Drive NE	36	6	6
C4	West A Street / Emerald Drive NW	36	6	6
C4	West A Street / South Emerald Oak Drive SE	36	6	6
C4	West A Street / South Emerald Oak Drive SW	36	6	6
C4	West C Street / Danny Drive NE	100	0	5
C4	West C Street / Danny Drive NW	100	0	5
C4	West C Street / Dawn Circle NW	100	0	6
C4	West C Street / Dawn Circle NE	100	0	6
C4	West C Street / Dawn Circle SW	100	0	6
C4	West C Street / Fumasi Drive NE	100	0	6
C4	West C Street / Fumasi Drive NW	100	0	6
C4	West C Street / Rowland Court NE	100	0	6
C4	West C Street / Rowland Court NW	100	0	6
C4	West C Street / Sasha Rose NE	100	0	6
C4	West C Street / Sasha Rose NW	100	0	6
C4	West C Street / Sasha Rose SE	100	0	6
C4	West C Street / Sasha Rose SW	100	0	6
C4	West C Street / Wagon Way NW	36	6	6
C4	West C Street / Wagon Way NE	36	6	6
C4	West C Street / Wagon Way SE	36	6	6
C4	West C Street / Wagon Way SW	36	6	6
C4	West E Street / Range Way	100	0	5
C4	West E Street / Village Run Drive E	100	0	5
C4	West E Street / Village Run Drive W	100	0	5
C9	White Chapel Drive / Maugham Drive SE	100	0	6
C9	White Chapel Drive / Maugham Drive SW	100	0	6
C9	Wicker Way / Ashboro Lane N	100	0	6
C9	Wicker Way / Ashboro Lane S	100	0	6
C3	Wilder Way / Kost Road SE	100	0	6
C3	Wilder Way / Kost Road SW	100	0	6
C3	Wilder Way / McCauley Way SE	100	0	6
C3	Wilder Way / McCauley Way NE	100	0	6
C3	Wilder Way / Wilder Way N	100	0	6

Draft

INTERSECTION PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C3	Wilder Way / Wilder Way S	100	0	6
C6	Wildflower Drive / Oberlin Way N	100	0	6
C6	Wildflower Drive / Oberlin Way S	100	0	6
C11	Winn Drive / Emerald Vista Drive N	100	0	5
C11	Winn Drive / Emerald Vista Drive S	100	0	6
C3	Wise Way / Wilder Way S	100	0	6
C3	Wise Way / Wilder Way NE	100	0	6
C3	Wise Way / Wilder Way SE	100	0	6
C6	Wren Lane / Wren Court E	100	0	6
C6	Wren Lane / Wren Court W	100	0	6
C4	Wristen Way / Mc Tucker Drive NE	36	6	6
C4	Wristen Way / Mc Tucker Drive SE	36	6	6
C4	Wristen Way / Wamsley Court NW	36	6	6
C4	Wristen Way / Wamsley Court SW	36	6	6

Draft

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
	2nd Street			
C4	2nd Street (A Street - C Street)	100	0	2
C4	2nd Street (C Street - E Street)	6	3	2
C4	2nd Street (E Street - F Street)	100	0	2
	3rd Street			
C4	3rd Street (A Street - C Street)	5	1	5
C4	3rd Street (C Street - E Street0	5	1	5
C4	3rd Street (E Street - F Street)	5	1	5
	4th Street			
C4	4th Street (A Street - C Street)	3	1	3
C4	4th Street (C Street - E Street)	3	1	3
C4	4th Strete (E Street - F Street)	3	1	3
C4	4th Street (F Street - H Street)	3	1	3
	5th Street			
C4	5th Street (A Street - C Street)	3	1	3
C4	5th Street (C Street - E Street)	3	1	3
C4	5th Street (E Street - F Street)	3	1	3
C4	5th Street (F Street - G Street)	3	1	3
	6th Street			
C5	6th Street (A Street - C Street)	6	1	6
C5	6th Street (C Street - E Street)	6	1	6
C5	6th Street (E Street - F street)	6	1	6
C5	6th Street (F Street - G Street)	6	1	6
	7th Street			
C5	7th Street (A Street - C Street)	3	1	3
C5	7th Street (C Street - D Street)	3	1	3
	A Street			
C4	A Street (Fairway Drive - Lincoln Way)	6	1	6
C4	A Street (Lincoln Way - Oak Avenue)	100	0	6
C4	A Street (Oak Avenue - McFarland Street)	6	1	6
C4	A Street (McFarland - Emerald Drive)	6	1	6
C4	A Street (Emerald Drive - Emerald Oak Drive)	6	1	6
	A Street West			

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C4	A Street West (Emerald Oak Drive - Fumasi Drive)	100	0	6
C4	A Street West (Fumasi Drive - Sparrow Drive)	100	0	6
	Adare Way			
C10	Adare Way (Stockton Boulevard - Fermoy Way)	6	1	6
C10	Adare Way (Fermoy Way - Emerald Vista Drive)	6	1	6
	Aldwych Court			
C9	Aldwych Court (Maugham Drive)	6	1	6
	Alice Rae Circle			
C6	Alice Rae Circle (Victorian Park Drive - Victorian Park Drive)	18	3	6
	Allport Drive			
C4	Allport Drive (McTucker Drive - Wristen Way)	6	1	6
C4	Allport Drive (Wristen Way - Driscol Drive)	6	1	6
	Almanor Way			
C9	Almanor Way (Canyon Creek Way - Summit Lakes Way)	6	1	6
	Almo Court			
C6	Almo Court (Emerald Drive)	6	1	6
	Almond Court			
C5	Almond Court (H Street)	6	1	6
	Alpen Rose Way			
C6	Alpen Rose Way (Sparrow Drive - Dasiy Drive)	6	1	6
	Alta Vista Court			
C11	Alta Vista Court (Emerald Vist Drive)	6	1	6
	Amador Avenue			
C7	Amador Avenue (Nathaniel Avenue - Ron Way)	6	1	6
C7	Amador Avenue (Ron Way - Lincoln Way North)	6	1	6
C7	Amador Avenue (Linclon Way North - Elm Avenue)	6	1	6
	Ambrogio Way			
C9	Amborgio Way (Carillion Boulevard - Killebrew Way)	6	1	6
	Amor Court			
C6	Amor Court (Emerald Oak Drive)	6	1	6
	Arlene Court			
C10	Arlene Court (Fermoy Way)	6	1	6
	Armstrong Way			

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C11	Armstrong Way (Holmsdale Way - Duncraig Way)	6	1	6
	Arnett Way			
C9	Arnett Way (Stenton Way - Conwell Court)	6	1	6
C9	Arnett Way (Conwell Court - Cold Brook Way)	6	1	6
	Ashboro Lane			
C9	Ashboro Lane (Stockton Boulevard - Lyonia Drive)	6	1	6
	Ashley Way			
C6	Ashley Way (Sunshine Drive - Elm Avenue West)	6	1	6
	Athy Court			
C12	Athy Court (Fermoy Way)	6	1	6
	Avondale Court			
C11	Avondale Court (Emerald Vista Drive)	6	1	6
	Ayers Lane			
C9	Ayers Lane (Carol Drive - Nathaniel Drive)	6	1	6
	B Street			
C4	B Street (2nd Street - 4th Stree)	100	0	6
C4	B Street (4th Street - 6th Street)	6	1	6
C4	B Street (6th Street - Lincoln Way North)	6	1	6
	Baker Court			
C9	Baker Court (Roundstone Drive)	6	1	6
	Balboa Court			
C11	Balboa Court (Emerald Vista Drive)	6	1	6
	Banff Court			
C6	Banff Court (Brody Drive)	6	1	6
	Barsetti Court			
C9	Barsetti Court (Stoneygate Drive)	6	1	6
	Bateman Court			
C11	Bateman Court (Bateman Way)	6	1	6
	Bateman Way			
C11	Bateman Way (Elk Hills Drive - Hepworth Drive)	6	1	6
	Bay Heights Court			
C13	Bay Heigths Court (Beaver Park Way)	12	2	6
	Bay Landing Way			

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C11	Bay Landing Way (Bay Shore Drive - Marina Bay Court)	6	1	6
C11	Bay Landing Way (Marina Bay Court - Bay Terrace Drive)	6	1	6
	Bay Shore Drive			
C11	Bay Shore Drive (Lake Park Avenue - Lake Canyone Avenue)	6	1	6
C11	Bay Shore Drive (Lake Canyone Avenue - Bay Landing Way)	6	1	6
C11	Bay Shore Drive (Bay Landing Way - Elk Hills Drive)	6	1	6
C11	Bay Shore Drive (Elk Hills Drive - Blackwell Drive)	6	1	6
	Bay Terrace Drive			
C11	Bay Terrace Drive (Breakers Drive - Bay Vista Court)	2	1	2
	Bay Vista Court			
C11	Bay Vista Court (Breakers Court)	2	1	2
	Beaver Park Way			
C11	Beaver Park Way (Lake Canyon Avenue - Moose Creek Way)	36	6	6
C11	Beaver Park Way (Moose Creek Way - Twin Hills Drive)	36	6	6
	Beeler Way			
C11	Beeler Way (Parnel Way - Norbury Way)	6	1	6
C11	Beeler Way (Norbury Way - Cottrel Way)	6	1	6
	Belfast Court			
C12	Belfast Court (Fermoy Way)	6	1	6
	Benner Court			
C2	Benner Court (1st Street)	5	1	5
	Beno Court			
C7	Beno Court (Wendy Hope Drive)	6	1	6
	Benteen Way			
C9	Benteen Way (Cedar Flat Way - Vintage Oak Avenue)	6	1	6
	Bentwood Drive			
C13	Bentwood Drive (Stormwood Avenue - Amberhill Avenue)	6	1	6
	Bernal Road			
C3	Bernal Road (Cornell Road - Ranch Road)	6	1	6
	Bernier Circle			
C9	Benrier Circle (Amador Avenue - Nathaniel Avenue)	6	1	6
	Big Jake Way			
C4	Big Jake Way (Wagon Way - Emerald Oak Drive South)	6	1	6

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
	Biloxi Park Court			
C13	Biloxi Park Court (Parkl Heights Drive)	6	1	6
	Birch Court			
C11	Birch Court (Emerald Vista Drive)	6	1	6
	Black Canyon Court			
C11	Black Canyon Court (Cedar Canyon Court)	6	1	6
	Blackhurst Drive			
C9	Blachhurst Drive (Tottenham Drive - Whitechapel Drive)	6	1	6
	Blackwell Way			
C11	Blackwell Way (Charsley Way - Bay Shore Drive)	6	1	6
	Bluebell Court			
C6	Blebell Court (Daisy Drive)	6	1	6
	Boessow Road			
C5	Boessow Road (Crystal Way - Frontage Road)	6	1	6
	Bonanza Drive			
C3	Bonanza Drive (Ranch Road - Chisholm Trail)	6	1	6
	Branding Iron Way			
C4	Branding Iron Way (Stetson Way - Wagon Way)	6	1	6
	Breakers Drive			
C13	Breakers Drive (Park Terrace Drive - Marine Bay Drive)	6	1	6
	Bridle Path			
C3	Bridle Path (Chishom Trail - Ranch Road)	6	1	6
	Brodie Drive			
C6	Brodie Drive (Emerald Oak Drive - Emerald Drive)	6	1	6
C6	Brodie Drive (Emerald Drive - Oberlin Way)	6	1	6
	Brodiewest Court			
C6	Brodiewest Court (Emererald Oak Drive)	24	4	6
	Buttercup Circle			
C11	Buttercup Circle (Vintage Oak Avenue - Vintage Oak Avenue)	24	4	6
	C Street			
C4	C Street (Crystal Way - Civic Drive)	12	4	3
C4	C Street (Civic Drive - Lincoln Way South)	100	0	3
C4	C Street (Lincoln Way South - 5th Street)	12	4	3
C4	C Street (5th Street - 3rd Street)	12	4	3

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C4	C Street (3rd Street - Wagon Way)	12	4	3
C4	C Street (Wagon Way - Range Way)	12	4	3
C4	C Street (Range Way - Rio Mesa Way)	12	4	3
	Camellia Way			
C7	Camellia Way (A Street - Wendy Hope Drive)	12	2	6
C7	Camellia Way (Wendy Hope Drive - Park Avenue)	12	2	6
	Canyon Creek Way			
C9	Canyon Creek Way (Summit Lakes Way - Cold Brook Way)	30	5	6
	Cardoso Court			
C2	Cardoso Court (Maria Way)	36	6	6
	Cardoso Drive			
C2	Cardoso Drive (Maria Way - 1st Street)	36	6	6
	Carillion Boulevard			
C9	Carillion Boulevard (Vauxhall Avenue - Chelsham Avenue)	36	6	6
C9	Carillion Boulevard (Chelsham Avenue - Di Maggio Way)	36	6	6
C9	Carillion Boulevard (Di Maggio Way - Vintage Oak Avenue)	36	6	6
C9	Carillion Boulevard (Vintage Oak Avenue - Walnut Avenue)	36	6	6
C9	Carillion Boulevard (Walnut Avenue - Elk Hills Drive)	36	6	6
C9	Carillion Boulevard (Elk Hills Drive - Lake Canyon Avenue)	36	6	6
C9	Carillion Boulevard (Lake Canyone Avenue - Twin Cities Road)	36	6	6
	Carlo Court			
C4	Carlo Court (Meadow View Drive)	36	6	6
	Carol Drive			
C2	Carol Drive (Amador Avenue - Ayers Lane)	36	6	6
	Caroline Avenue			
C5	Caroline Avenue (Fairway Drive - Pine Street)	12	6	2
C5	Caroline Avenue (Pine Street - Civic Drive)	12	6	2
C5	Caroline Avenue (Civic Drive - Chabolla Avenue)	100	0	2
C5	Caroline Avenue (Chabolla Avenue - Lincoln Way South)	100	0	2
	Carpinteria Drive			
C13	Carpinteria Drive (Monterey Bay Court - Park Terrace Drive)	24	4	6
	Carr Way			
C6	Carr Way (Alice Rae Circle - Alice Rae Circle)	24	4	6
	Casado Drive			

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C5	Casado Drive (Glendale Avenue - Meladee Lane)	30	6	5
	Caversham Way			
C11	Caversham Way (Lampard Way - Malton Way)	12	2	6
	Cedar Canyon Circle			
C11	Cedar Canyon Circle (Olive Canyon Drive - Olive Canyon Drive)	12	2	6
	Cedar Flat Avenue			
C9	Cedar Flat Avenue (Benteen Way - Vintage Oak Avenue)	42	7	6
C9	Cedar Flat Avenue (Vintage Oak Avenue - Colson Court)	42	7	6
	Chabolla Avenue			
C5	Chabolla Avenue (Caroline Avenue - 5th Street)	15	5	3
	Chaps Court			
C4	Chaps Court (Wagon Way)	18	3	6
	Charsley Way			
C11	Charsley Way (Blackwell Way - Piermont Way)	18	3	6
	Chase Drive			
C3	Chase Drive (Chisholm Trail)	18	3	6
	Chelsham Avenue			
C9	Chelsham Avenue (Stoneygate Drive - Portland Lane)	36	6	6
C9	Chelsham Avenue (Portland Lane - Marendg Road)	36	6	6
	Chisholm Trail			
C3	Chisholm Trail (Bridle Path - Tradepost Trail)	36	6	6
	Church Street			
C5	Church Street (H Street - G Street)	36	6	6
	Cimmaron Court			
C10	Cimmaron Court (Emerald Vista Drive)	36	6	6
	Cindy Lane			
C2	Cindy Lane (Tudor Street - 1st Stret)	100	0	6
	Cinnamon Drive			
C6	Cinnamon Drive (Sparrow Drive - Streling Oak Drive)	36	6	6
	Civic Drive			
C5	Civic Drive (Caroline Avenue - C Street)	6	6	1
	Claybury Court			
C11	Claybury Court (Vintage Oak Avenue)	36	6	6
	Cleland Court			

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C9	Cleland Court (Colson Way)	36	6	6
	Clover Court			
C6	Clover Court (Lorna Way)	36	6	6
	Cobble Hill Way			
C11	Cobble Hill Way (Summit Lakes Way - Summit Lakes Way)	18	3	6
	Cobden Court			
C11	Cobden Court (Rossburn Way)	24	4	6
	Cobden Way			
C11	Cobden Way (Elk Hills Drive - Rossburn Way)	24	4	6
	Coburg Court			
C9	Coburg Court (Cedar Flat Avenue)	24	4	6
	Cold Brook Way			
C9	Cold Brook Way (Canyon Creek Way - Arnett Way)	24	4	6
	Cold Brook Court			
C9	Cold Brook Court (Canyon Creek Way))	24	4	6
	Colmore Way			
C9	Colmore Way (Arnett Way - Trammel Way)	24	4	6
	Colson Way			
C9	Colson Way (Cedar Flat Avenue - Arnett Way)	24	4	6
	Conwell Court			
C9	Conwell Court (Arnett Way)	24	4	6
	Cornell Road			
C3	Cornell Road (5th Street - Bernal Road)	24	4	6
	Corral Place			
C3	Corral Place (Bonanza Drive - Tradepost Trail)	24	4	6
	Corvey Circle			
C10	Corvey Circle (Fermoy Way - Fermoy Way)	24	4	6
	Cottrell Way			
C11	Cottrell Way (Jordine way - Presbury Way)	24	4	6
	Cottrell Court			
C11	Cottrell Court (Presbury Way)	24	4	6
	Courtenay Court			
C13	Courtenay Court (Tierra Creek Drive)	24	4	6

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
	Creekside Way			
C2	Creekside Way (Kost Road - Meadowview Road)	100	0	5
	Crescent Court			
C6	Crescent Court (Crescent Drive)	24	4	6
	Crescent Drive			
C6	Crescent Drive (Simons Street - Elm Avenue)	24	4	6
	Crow Creek Drive			
C2	Crow Creek Drive (1st Street - Raven Brook Drive)	24	4	6
	Crystal Way			
C5	Crystal Way (99 Off Ramp - Boessow Road)	24	4	6
C5	Crystal Way (Boessow Road - Fairway Drive)	24	4	6
	Curtiss Court			
C7	Curtiss Court (Wendy Hope Drive)	24	4	6
	D Street			
C4	D Street (4th Street - 6th Street)	12	4	3
C4	D Street (6th Street - Licoln Way South)	12	4	3
	Daisy Court			
C6	Daisy Court (Daisy Drive)	24	4	6
	Daisy Drive			
C6	Daisy Drive (Daisy Court - Edelweiss Way)	24	4	6
	Danny Drive			
C4	Danny Drive (Oakwilde Street - C Street West)	24	4	6
	Dawn Circle			
C4	Dawn Circle (Danny Drive - C Street West)	24	4	6
	Dawnwood Drive			
C13	Dawnwood Drive (Stormwood Avenue - Amberhill Avenue)	24	4	6
	Delane Drive			
C9	Delane Drive (Carol Drive - Bernier Circle)	24	4	6
	Denier Court			
C9	Denier Court (Vauxhall Avenue)	24	4	6
	Di Maggio Court			
C9	Di Maggio Court (Carillion Boulevard - Killebrew Way)	24	4	6
	Dickens Drive			

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C9	Dickens Drive (Hamstead Drive - Marengo Road)	24	4	6
	Doradell Court			
C11	Doradell Court (Strathhaven Way)	24	4	6
	Doradell Way			
C11	Doradell Way (Strathhaven Way - Elk Hills Drive)	24	4	6
	Dover Drive			
C2	Dover Drive (Tudor Street - Meadowview Drive)	100	0	6
	Downing Drive			
C2	Downing Drive (Tudor Street - 1st Street)	100	0	6
C2	Downing Drive (1st Street - Gaylon Way)	24	4	6
	Driscol Drive			
C4	Driscol Drive (Allport Drive - Rio Mesa Way)	24	4	6
	Duncraig Way			
C11	Duncraig Way (Armstrong Way - Malton Way)	24	4	6
	Dutch Harbor Court			
C11	Dutch Harbor Court (Elk Hills Drive)	24	4	6
	E Street			
C4	E Street (Range Way - Wagon Way)	24	4	6
C4	E Street (Wagon Way - 2nd Street)	24	4	6
C4	E Street (2nd Street - 3rd Street)	24	4	6
C4	E Street (4th Street - 6th Street)	100	0	
C4	E Street (6th Street - S Lincoln Way)	100	0	6
	East Stockton Boulevard			
C10	East Stockton Boulevard (Twin Cities Road - Adare Way)	24	4	6
C10	East Stockton Boulevard (Adare Way - Walnut Avenue)	24	4	6
C10	East Stockton Boulevard (Walnut Avenue - Winn Drive)	24	4	6
C10	East Stockton Boulevard (Winn Drive - Ashboro Lane)	24	4	6
C10	East Stockton Boulevard (Ashboro Lane - Ayers Lane)	24	4	6
C10	East Stockton Boulevard (Ayers Lane - Amador Avenue)	24	4	6
	Edelweiss Way			
C6	Edelweiss Way (Sparrow Drive - Dasiy Drive)	24	4	6
C6	Edelweiss Way (Daisy Drive - Elm Avenue)	24	4	6
	Elderwood Drive			

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C13	Elderwood Drive (Hiddenwood Drive - Ivywood Drive)	24	4	6
	Elk Hills Drive			
C11	Elk Hills Drive (Fermoy Way - Dutch Harbor Court)	24	4	6
C11	Elk Hills Drive (Dutch Harbor Court - Vintage Oak Avenue)	24	4	6
C11	Elk Hills Drive (Vintage Oak Avenue - Rossburn Way)	24	4	6
C11	Elk Hills Drive (Rossburn Way - Carillion Boulevard)	24	4	6
C11	Elk Hills Drive (Carillion Boulevard - Bay Shore Drive)	24	4	6
C11	Elk Hills Drive (Bay Shore Drive - Lampard Way)	24	4	6
C11	Elk Hills Drive (Lampard Way - Walnut Avenue)	24	4	6
	Elm Avenue			
C6	Elm Avenue (Sparrow Drive - Grouse Drive)	24	4	6
C6	Elm Aevnue (Grouse Drive - Emerald Oak Drive)	24	4	6
C6	Elm Avenue (Emerald Oak Drive - McFarland Street)	24	4	6
C6	Elm Avenue (McFarland Street - Industrial Drive)	100	0	6
C6	Elm Avenue (Industrial Drive - N Lincoln Way)	100	0	6
	Elsworth Court			
C11	Elsworth Court (Elk Hills Drive)	24	4	6
	Embleton Court			
C11	Embleton Court (Shalford Way)	24	4	6
	Emerald Court			
C6	Emerald Court (Brodie Drive)	24	4	6
	Emerald Drive			
C4	Emerald Drive (Brodie Drive - Almo Court)	24	4	6
C4	Emerlad Drive (Almo Court - A Street)	24	4	6
	Emerald Oak Drive			
C6	Emerald Oak Drive (Elm Avenue - Quail Hollow Drive)	24	4	6
C6	Emerald Oak Drive (Quail Hollow Drive - Amor Court)	24	4	6
C6	Emerlad Oak Drive (Amor Court - West A Street)	24	4	6
	Emerald Vista Drive			
C9	Emerald Vista Drive (Adare Way - Walnut Avenue)	20	4	5
C9	Emerald Vista Drive (Walnut Avenue - Alta Vista Court)	20	4	5
C9	Emerlad Vista Drive (Alta Vista Court - Rachel Drive)	20	4	5
	Enterprise Way			

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C6	Enterprise Way (N Lincoln Way)	24	4	6
	Eric Circle			
C2	Eric Circle (New Hope Road - New Hope Road)	25	5	5
	Ewell Court			
C9	Ewell Court (Bernier Circle)	30	5	6
	F Street			
C4	F street (1st Street - 3rd Street)	30	5	6
C4	F Street (3rd Street - 5th Street)	30	5	6
C4	F Street (5th Street - S Lincoln Way)	30	5	6
	Fairsite Court			
C5	Fairsite Court (Church Street)	30	5	6
	Fairway Drive			
C5	Fairway Drive (Church Street)	30	5	6
	Fawcett Court			
C11	Fawcett Court (Blackwell Way)	30	5	6
	Fermoy Way			
C10	Fermoy Way (Elk Hills Drive - Arlene Court)	30	5	6
C10	Fermoy Way (Adare Way - Lake Canyon Avenue)	30	5	6
C10	Fermoy Way (Lake Canyon Avenue - Twin Cities Road)	30	5	6
	Fern Court			
C6	Fern Court (Lorna Way)	30	5	6
	Fernando Way			
C2	Fernando Way (Cardosa Drive - Pestana Drive)	36	6	6
	Finch Drive			
C6	Finch Drive (Teal Lane - Partridge Drive)	30	5	6
	Findon Court			
C9	Findon Court (Arnett Way)	30	5	6
	1st Street			
C2	1st Street (Kost Road - Cardosa Drive)	100	0	6
C2	1st Street (Cardosa Drive - Cindy Lane)	100	0	6
C2	1st Street (Cindy Lane - F Street)	100	0	6
	Foxtrotter Way			
C13	Foxtrotter Way (Pinto Trail Drive - Twin Cities Road)	36	6	6

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
	Fran Court			
C9	Fran Court (Vauxhall Avenue)	36	6	6
	Franston Street			
C5	Franston Street (Crystal Way - Crystal Way)	36	6	6
	Fulham Court			
C9	Fulham Court (Maugham Drive)	36	6	6
	Fumasi Drive			
C4	Fumasi Drive (West A Street - West C Street)	12	6	2
	G Street			
C5	G Street (5th Street - South Lincoln Way)	36	6	6
	Gary Avenue			
C7	Gary Avenue (Palin Avenue - Lois Avenue)	36	6	6
	Gaylon Way			
C2	Gaylon Way (Pestana Drive - Downing Drive)	36	6	6
	Geranium Circle			
C6	Geranium Circle (Sparrow Drive - Sparrow Drive)	36	6	6
	Gerling Court			
C11	Gerling Court (Tierra Creek Drive)	36	6	6
	Germaine Drive			
C2	Germaine Drive (Fernando Drive - Gaylon Way)	36	6	6
	Gibralter Court			
C9	Gibralter Court (Vauxhall Avenue)	36	6	6
	Glendale Avenue			
C5	Glendale Avenue (Meladee Avenue - Fairway Drive)	36	6	6
	Golden Heights Drive			
C12	Golden Heights Drive (Beaver Park Way - Lake Canyon Avenue)	30	6	5
	Goshawk Drive			
C6	Goshwak Drive (Sparrow Drive)	36	6	6
	Griffey Way			
C9	Griffey Way (Ambrogio Way - Di Maggio Way)	36	6	6
	Grouse Drive			
C6	Grouse Drive (Quail Hollow Drive - Elm Avenue)	36	6	6
	Guild Street			

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C4	Guild Street (2nd Street - 3rd Street)	36	6	6
	H Street			
C5	H Street (4th Street - Church Street)	36	6	6
	Halton Court			
C11	Halton Court (Parnel Way)	36	6	6
	Hamel Way			
C3	Harnel Way (Kost Road - Wilder Way)	36	6	6
	Hamstead Drive			
C9	Hamstead Drive (Chelsham Avenue - Walworth Drive)	36	6	6
C9	Hamstead Drive (Walworth Drive - Wallington Drive)	36	6	6
	Hanoverian Circle			
C13	Hanoverian Circle (Pinto Trail Drive - Pinto Trail Drive)	36	6	6
	Hansard Court			
C9	Hansard Court (Benteen Way)	36	6	6
	Happy Court			
C5	Happy Court (Casado Drive)	30	6	5
	Hepworth Way			
C11	Hepworth Way (Koralla Way - Bateman Court)	36	6	6
	Hickey Way			
C11	Hickey Way (Bay Shore Drive - Starbrook Drive)	36	6	6
	Hiddenwood Drive			
C13	Hiddenwood Drive (Stormwood Avenue - Amberhill Avenue)	36	6	6
	East Hill Court			
C13	East Hill Court (Ivywood Drive)	36	6	6
	West Hill Court			
C13	West Hill Court (Hiddenwood Drive)	36	6	6
	Holly Court			
C2	Holly Court (Downing Drive)	36	6	6
	Holmisdale Way			
C11	Holmisdale Way (Taplin Way - Aemstrong Way)	36	6	6
	Holsteiner Court			
C13	Holsteiner Court (Pinto Trail Drive)	36	6	6
	Howard Court			

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C11	Howard Court (Bay Landing Way)	36	6	6
	Industrial Court			
C8	Industrial Court (Industrial Drive)	36	6	6
	Industrial Drive			
C6	Industrial Drive (Pringle Avenue - Live Oak Avenue)	36	6	6
	Ivywood Drive			
C13	Ivywood Drive (Stormwood Avenue - Elderwood Drive)	36	6	6
C13	Ivywood Drive (Elderwood Drive - Amberhill Avenue)	36	6	6
	Janine Court			
C2	Janine Court (Crow Creek Drive)	36	6	6
	Jennifer Court			
C10	Jennifer Court (Fermoy Way)	36	6	6
	Jonathon Court			
C4	Jonathon Court (Oakwilde Street)	36	6	6
	Jordine Way			
C11	Jordine Way (Elk Hills Drive - Presbury Way)	36	6	6
C11	Jordnie Way (Presbury Way - Beeler Way)	36	6	6
	Joy Drive			
C3	Joy Drive (G Street - H Street)	36	6	6
	June Court			
C13	June Court (Stream Drive)	36	6	6
	Justin Court			
C4	Justin Court (Oakwilde Street)	36	6	6
	Kandy Street			
C2	Kandy Street (Tudor Street - Creekside Way)	100	0	6
	Kelly Drive			
C3	Kelly Drive (Joy Drive)	36	6	6
	Kent Street			
C2	Kent Street (Tudor Street - Cindy Lane)	36	6	6
	Killebrew Way			
C9	Kilebrew Way (Ambrogio Way - Marichal Way)	36	6	6
C9	Killebrew Way (Marichal Way - Di Maggio Way)	36	6	6
	Koralla Court			

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C11	Koralla Court (Hepworth Way)	36	6	6
	Koralla Way			
C11	Koralla Way (Hepworth Way - Cobden Way)	36	6	6
	Kost Road			
C2	Kost Road (South Lincoln Way - Wilder Way)	36	6	6
C2	Kost Way (Raven Brook Drive - 1st Street)	36	6	6
C2	Kost Way (1st Street - Tudor Street)	36	6	6
	La Quita Court			
C9	La Quita Court (Vauxhall Avenue)	36	6	6
	Labrador Court			
C4	Labrador Court (West E Street)	36	6	6
	Lake Canyon Avenue			
C13	Lake Canyon Avenue (Fermoy Way - Bay Heights Drive)	12	6	2
C13	Lake Canyon Avenue (Fermoy Way - Cape Canyon Way)	12	6	2
C13	Lake Canyon Avenue (Cape Canyon Way - Carillion Boulevard)	12	6	2
C13	Lake Canyon Avenue (Carillion Boulevard- Tierra Creek Drive)	12	6	2
C13	Lake Canyone Avenue (Tierra Creek Drive - Bay Shore Drive)	12	6	2
	Lake Park Avenue			
C13	Lake Park Avenue (Carillion Boulevard - Bay Shore Drive)	30	6	5
C13	Lake Park Avenue (Bay Shore Drive - Park Terrace Drive)	30	6	5
C13	Lake Park Avenue (Park Terrace Drive - Marengo Road)	30	6	5
	Lampard Way			
C11	Lampard Way (Elk Hills Drive - Caversham Way)	12	6	2
	Lanigan Court			
C11	Lanigan Court (Benteen Way)	36	6	6
	Lapwing Lane			
C6	Lapwing Lane (Cinnamon Drive - Spoonhill Lane)	36	6	6
	Larait Court			
C3	Lariat Court (Lariat Loop)	36	6	6
	Larkspur Court			
C6	Larkspur Court (Edelweiss Way)	36	6	6
	Lariat Loop			
C3	Lariat Loop (Ranch Road - Ranch Road)	36	6	6

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
	Lauchert Place			
C9	Lauchert Place (Vauxhall Avenue)	36	6	6
	Lavender Court			
C6	Lavender Court (Edelweiss Way)	36	6	6
	Lewins Court			
C13	Lewins Court (Breakers Drive)	36	6	6
	Liebig Court			
C9	Liebig Court (Wallington Drive)	36	6	6
	Lincoln Way			
C3	Lincoln Way (Kost Road - Ranch Road)	36	6	6
C3	Lincoln Way (Singletree Court - Chabolla Avenue)	36	6	6
C3	Lincoln Way (Chabolla Avenue - E Street)	36	6	6
C3	Lincoln Way (E Street - C Street)	36	6	6
C3	Lincoln Way (C Street - A Street)	36	6	6
C3	North Lincoln Way (A Street - Wendy Hope Drive)	36	6	6
C3	North Lincoln Way (Wendy Hope Drive - Terrace Lane)	36	6	6
C3	North Lincolon Way (Terrace Lane - Amador Avenue)	36	6	6
C3	North Lincoln Way (Amador Avenue - Pringle Avenue)	36	6	6
	Lois Avenue			
C7	Lois Avenue (Gary Street - Myrtle Street)	36	6	6
	Lorna Way			
C6	Lorna Way (Sunshine Drive - Oberlin Drive)	36	6	6
	Los Flores Court			
C9	Los Flores Court (Emerald Vista Drive)	30	6	5
	Lyonia Drive			
C9	Lyonia Drive (Ashboro Lane - Trellis Lane)	36	6	6
	Mallard Drive			
C6	Mallard Drive (Sparrow Drive - Grouse Court)	36	6	6
	Malton Way			
C11	Malton Way (Duncraig Way - Holmisdale Way)	36	6	6
	Manton Court			
C9	Manton Court (Tremmel Way)	36	6	6
	Maple Street			

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C5	Maple Street (C Street - Caroline Avenue)	18	6	3
	Marengo Road			
C9	Marengo Road (Twin Cities Road - Lake Park Avenue)	36	6	6
C9	Marengo Road (Walnut Avenue - Elk Hills Drive)	36	6	6
C9	Marengo Road (Maugham Drive - Vauxhall Avenue)	36	6	6
	Maria Way			
C2	Maria Way (Downing Drive - Pestana Drive)	36	6	6
	Marichal Way			
C9	Marichal Way (Griffey Way - Killebrew Way)	36	6	6
	Marine Bay Drive			
C13	Marine Bay Drive (Marine Bay Court - Bay Landing Way)	36	6	6
	Market Street			
C5	Market Street (A Street - C Street)	36	6	6
	Matthew Court			
C4	Matthew Court (Big Jake Way)	36	6	6
	Maugham Court			
C9	Maugham Court (Portland Court)	36	6	6
	Maugham Road			
C9	Maugham Road (Maugham Court - Marengo Road)	36	6	6
	Mc Tucker Drive			
C4	Mc Tucker Drive (Wristen Way - New Hope Road)	30	6	5
	McAlta Court			
C9	McAlta Court (Hamstead Drive)	36	6	6
	McCauley Way			
C3	McCauley Way (Wilder Way - Wilder Way)	36	6	6
	McFarland Street			
C6	McFarland Street (Elm Avenue - Trudy Way)	36	6	6
C6	McFarland Street (Trudy Way - A Street)	100	0	6
	Meadowview Drive			
C2	Meadowview Drive (Cindy Lane - Creekside Way)	100	0	6
C2	Meadowview Drive (Creekside Way - Kost Road)	100	0	6
	Meladee Lane			
C5	Meladee Lane (South Lincoln Way - Glendale Avenue)	30	6	5

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C5	Meladee Lane (Glendale Avenue - Caroline Avenue)	30	6	5
	Mildred Avenue			
C7	Mildred Avenue (Elm Avenue - Simons Street)	36	6	6
	Millson Court			
C11	Millson Court (Bateman Way)	36	6	6
C13	**Monterey Bay Court**			
C13	Monterey Bay Court (Lake Park Avenue)	30	6	5
	Moose Creek Way			
C11	Moose Creek Way (Emerlad Vista Drive - Beaver Park Way)	36	6	6
C13	**Morgans Ranch Circle**			
C13	Morgans Ranch Circle (Pinto Trail Drive - Pinto Trail Drive)	36	6	6
	Myrtle Avenue			
C6	Myrtle Avenue (Oak Avenue - Palin Avenue)	100	0	3
C6	Myrtle Avenue (Palin Avenue - North Lincoln Way)	100	0	3
	Nathaniel Avenue			
C9	Nathaniel Avenue (Ayers Lane - Amador Avenue)	36	6	6
	Neville Way			
C11	Neville Way (Shalford Way - Walnut Avenue)	36	6	6
	New Hope Road			
C2	New Hope Road (1st Street - Village Run Drive)	30	6	5
C2	New Hope Road (Village Run Drive - McTucker Drive)	30	6	5
	Norbury Way			
C11	Norbury Way (Beeler Way - Elk Hills Drive)	36	6	6
	Oak Avenue			
C4	Oak Avenue (Elm Avenue - Simons Street)	18	6	3
C4	Oak Avenue (Simons Street - A Street)	18	6	3
	Oak Wilde Street			
C4	Oak Wilde Street (Fumasi Drive - Jonathan Court)	100	0	2
	Oak Wilde Street (Jonathan Court - South Emerald Oak Drive)	100	0	2
C6	**Oberlin Way**			
C6	Oberlin Way (Sunshine Drive - Lorna Way)	36	6	6
C6	Oberlin Way (Lorna Way - Trent Drive)	36	6	6
	Oldenburg Way			

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C13	Oldenburg Way (Pinto Trail Drive East/ West)	36	6	6
	Olive Canyon Drive			
C11	Olive Canyon Drive (Beaver Park Way - Cedar Canyon Circle)	36	6	6
	Olive Court			
C5	Olive Court (H Street)	36	6	6
	Padbury Court			
C11	Padbury Court (Elk Hills Drive)	36	6	6
	Paddington Circle			
C9	Paddinton Circle (Vauxhall Avenue - Vauxhall Avenue)	36	6	6
	Palin Avenue			
C7	Palin Avenue (Elm Avenue - Simons Street)	100	0	6
C7	Palin Avenue (Simons Street - Myrtle Street)	100	0	6
C7	Palin Avenue (Myrtle Street - A Street)	100	0	6
	Park Avenue			
C7	Park Avenue (Camellia Way - Terrace Lane)	36	6	6
	Park Avenue Court			
C7	Park Avenue Court (Park Avenue)	36	6	6
	Park Heights Drive			
C13	Park Heights Drive (Bay Shore Drive - Stream Drive)	36	6	6
	Stream Drive			
C13	Stream Drive (Stormwood Avenue - Park Valley Way)	36	6	6
	Park Terrace Drive			
C13	Park Terrace Drive (Twin Cities Road - Lake Park Avenue)	36	6	6
C13	Park Terrace Drive (Lake Park Avenue - Stream Drive)	36	6	6
C13	Park Terrace Drive (Stream Drive - Breakers Drive)	36	6	6
C13	Park Terrace Drive (Breakers Drive - Bay Vista Court)	36	6	6
C13	Park Terrace Drive (Bay Vista Court - Walnut Avenue)	36	6	6
	Park Valley Way			
C13	Park Valley Way (Park Heights Drive - Stream Drive)	36	6	6
	Parnel Way			
C11	Parnel Way (Elk Hills Drive - Beeler Way)	36	6	6
C11	Parnel Way (Beeler Way - Norbury Way)	36	6	6
	Partridge Drive			

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C6	Partidge Drive (Grouse Drive - Finch Drive)	36	6	6
	Pestana Drive			
C2	Pestana Drive (1st Street - Maria Way)	36	6	6
C2	Pestana Drive (Maria Way - Gaylon Way)	36	6	6
	Pheasant Drive			
C6	Pheasant Drive (Grouse Drive - Finch Drive)	36	6	6
	Piermont Court			
C11	Piermont Court (Piermont Way)	36	6	6
	Piermont Way			
C11	Piermont Way (Piermont Court - Action Way)	36	6	6
	Pine Street			
C5	Pine Street (C Street - Caroline Avenue)	6	6	1
	Pinto Trail Drive			
C13	Pinto Trail Drive (Foxtrotter Way - Oldenburg Way)	36	6	6
C13	Pinto Trail Drive (Oldenburg Way - Lake Canyon Avenue)	36	6	6
	Plains Court			
C4	Plains Court (Range Way)	36	6	6
	Poplar Street			
C6	Poplar Street (Oak Avenue)	36	6	6
C6	Poplar Street (Elm Avenue)	36	6	6
	Poppy Court			
C11	Poppy Court (Vintage Oak Avenue)	36	6	6
	Port Ashton Court			
C11	Port Ashton Court (Moose Creek Way)	36	6	6
	Portland Lane			
C9	Portland Lane (Maugham Drive - Chelsham Avenue)	36	6	6
	Prairie Court			
C10	Prairie Court (Emerald Vista Drive)	36	6	6
	Presbury Way			
C11	Presbury Way (Norbury Way - Cottrell Court)	36	6	6
	Pringle Avenue			
C8	Pringle Avenue (Industrial Drive - North Lincoln Way)	36	6	6
	Quail Hollow Drive			

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C6	Quail Hollow Drive (Sparrow Drive - Grouse Drive)	36	6	6
C6	Quail Hollow Drive (Grouse Drive - Emerald Oak Drive)	36	6	6
	Rachel Drive			
C9	Rachel Drive (Emerald Vista Drive - Cobble Hill Way)	36	6	6
	Ramon Court			
C4	Ramon Court (Emerald Drive)	36	6	6
	Ramon Drive			
C4	Ramon Drive (Emerald Drive - Emerald Oak Drive)	36	6	6
	Ranch Road			
C3	Ranch Road (South Lincoln Way - Bonanza Drive)	36	6	6
C3	Ranch Road (Bonanza Drive - Tradepost Trail)	36	6	6
	Ranford Court			
C11	Ranford Court (Norbury Way)	36	6	6
	Range Way			
C4	Range Way (West C Street - West E Street)	36	6	6
	Raven Brook Drive			
C2	Raven Brook Drive (Crow Creek Drive - Kost Road)	36	6	6
	Retriever Way			
C4	Retreiver Way (West E Street - West E Street)	36	6	6
	Rio Mesa Court			
C4	Rio Mesa Court (Range Way)	36	6	6
	Rio Mesa Way			
C4	Rio Mesa Way (Sasha Rose - Driscol Drive)	36	6	6
C4	Rio Mesa Way (Driscol Drive - Range Way)	36	6	6
	Ripken Avenue			
C9	Ripken Avenue (Ambrogio Way)	36	6	6
	Robin Court			
C6	Robin Court (Robin Lane)	36	6	6
	Robin Lane			
C6	Robin Lane (Elm Avenue - Pheasant Drive)	36	6	6
	Ron Way			
C6	Ron Way (Delane Drive - Amador Avenue)	36	6	6
	Rossburn Court			

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C11	Rossburn Court (Strathaven Way)	36	6	6
	Rossburn Way			
C11	Rossburn Way (Strathaven Way - Cobden Court)	36	6	6
	Rossi Drive			
C6	Rossi Drive (Emerald Oak Drive - Oberlin Drive)	36	6	6
	Roundstone Drive			
C9	Roundstone Drive (Stoneygate Drive - Stoneygate Drive)	36	6	6
	Rowland Court			
C4	Rowland Court (West C Street)	36	6	6
	Royal Court			
C6	Royal Court (Brodie Drive)	36	6	6
	Saddle Court			
C4	Saddle Court (Wagon Way)	36	6	6
	Sandpiper Drive			
C6	Sandpiper Drive (Grouse Drive - Mallard Drive)	36	6	6
	Sasha Rose			
C4	Sasha Rose (Fumasi Drive - West C Street)	12	6	2
	Saunders Court			
C13	Saunders Court (Stream Drive)	36	6	6
	Seaver Court			
C9	Seaver Court (Killebrew Way)	36	6	6
	Shalford Way			
C11	Shalford Way (Steele Way - Embleton Court)	36	6	6
	Shelduck Court			
C11	Shelduck Court (Shelduck Lane)	36	6	6
	Shelduck Lane			
C6	Shelduck Lane (Shelduck Court - Mallard Drive)	36	6	6
	Sherborne Court			
C9	Sherborne Court (Vauxhall Avenue)	36	6	6
	Silver Aspen Court			
C6	Silver Aspen Court (Sterling Grove Drive)	36	6	6
	Silver Cypress Court			
C6	Silver Cypress Court (Sterling Grove Drive)	36	6	6

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
	Silver Pine Court			
C6	Silver Pine Court (Sterling Grove Drive)	36	6	6
	Silver Spruce Court			
C6	Silver Spruce Court (Sterling Grove Drive)	36	6	6
	Silver Willow Court			
C6	Silver Willow Court (Sterling Grove Drive)	36	6	6
	Silverado Way			
C4	Silverado Way (New Hope Road - Spur Way)	36	6	6
	Simons Street			
C6	Simons Street (Oak Avenue - Palin Avenue)	36	6	6
C6	Simons Street (Palin Avenue - North Lincoln Way)	36	6	6
	Singletree Court			
C5	Singletree Court (South Lincoln Way)	36	6	6
	Slidell Park Court			
C13	Slidell Park Court (Park Heights Drive)	36	6	6
	Snow Lily Avenue			
C113	Snow Lily Avenue (Thornbridge Drive - Woodflower Court)	36	6	6
C13	Snow Lilly Avenue (Woodflower Court - Lake Canyon Avenue)	36	6	6
	South Emerald Oak Drive			
C4	South Emerald Oak Drive (West A Street - West C Street)	36	6	6
	Southdale Court			
C5	Southdale Court (South Lincoln Way - Meladee Lane)	36	6	6
	Spaans Drive			
C7	Spaans Drive (Enterprise Way - North Lincoln Way)	36	6	6
	Sparrow Drive			
C6	Sparrow Drive (Elm Avenue - Wren Drive)	36	6	6
C6	Sparrow Drive (Wren Drive - Cinnamon Drive)	36	6	6
C6	Sparrow Drive (Wren Drive - Cinnamon Drive)	36	6	6
C6	Sparrow Drive (Cinnamon Drive - West A Street)	36	6	6
	Speakers Court			
C9	Speakers Court (Vauxhall Avenue)	36	6	6
	Spoonbill Lane			
C6	Spoonbill Lane (Lapwing Lane - Sterling Grove Drive)	36	6	6

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
	Spree Court			
C4	Spree Court (Emerlad Drive)	36	6	6
	Spruce Avenue			
C4	Spruce Avenue (Victorian Park Drive - Spruce Avenue)	18	6	3
	Spur Way			
C4	Spur Way (West E Street - New Hope Road)	30	6	5
	Stampede Trail			
C3	Stampede Trail (Bonanza Drive - Tradepost Trail)	36	6	6
	Starbrook Drive			
C13	Starbrook Drive (Gerling Court - Hickey Way)	36	6	6
C13	Starbrook Drive (Hickey Way - Tierra Creek Drive)	36	6	6
	Steele Way			
C11	Steele Way (Park Terrace Drive - Shalford Way)	36	6	6
	Steep Rock Court			
C9	Steep Rock Court (Cobble Hill Way)	36	6	6
	Stefan Court			
C3	Stefan Court (Wilder Way)	36	6	6
	Stenton Court			
C9	Stenton Court (Trammel Way)	36	6	6
	Sterling Grove Drive			
C4	Sterling Grove Drive (Sparrow Drive - Silver Aspen Court)	36	6	6
C4	Sterling Grove Drive (Silver Aspen Court - Sterling Oak Drive)	36	6	6
C4	Sterling Grove Drive (Sterling Oak Drive - Silver Spruce Court)	36	6	6
	Sterling Oak Drive			
C6	Sterling Oak Drive (Cinnamon Drive - Sterling Grove Drive)	36	6	6
C6	Sterling Oak Drive (Sterling Grove Drive - West A Street)	36	6	6
	Stetson Way			
C4	Stetson Way (Branding Iron Way - West E Street)	36	6	6
	Stirrup Court			
C4	Stirrup Court (Wagon Way)	36	6	6
	Stoneygate Drive			
C9	Stonetgate Drive (Stoneygate Court - Roundstone Drive)	36	6	6
	Stormwood Avenue			

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C13	Stormwood Avenue (Ivywood Drive - Lake Park Avenue)	36	6	6
C13	Stormwood Drive (Lake Park Avenue - Bentwood Drive)	36	6	6
	Strathaven Way			
C11	Strathaven Way (Doradell Way - Rossburn Way)	36	6	6
	Sugarwood Court			
C9	Sugarwood Court (Vintage Oak Avenue)	36	6	6
	Summit Lakes Court			
C9	Summit Lakes Court (Almanor Way)	36	6	6
	Summit Lakes Way			
C9	Summit Lakes Way (Summit lakes Court - Vintage Oak Avenue)	36	6	6
C9	Summit Lakes Way (Vintage Oak Avenue - Cobble Hill Way)	36	6	6
	Sunset Drive			
C7	Sunset Drive (Elm Avenue - Elm Avenue)	36	6	6
	Sunshine Court			
C6	Sunshine Court (Sunshine Drive)	36	6	6
	Sunshine Drive			
C6	Sunshine Drive (Oberlin Drive - Rossi Drive)	36	6	6
C6	Sunshine Drive (Rossi Drive - Sunshine Court)	36	6	6
	Taggart Court			
C9	Taggart Court (Portland Lane)	36	6	6
	Tallega Court			
C9	Tallega Court (Colson Way)	36	6	6
	Taplin Way			
C11	Taplin Way (Colson Way)	12	6	2
	Teal Lane			
C6	Teal Lane (Finch Drive - Robin Lane)	36	6	6
	Terrace Lane			
C7	Terrace Lane (North Lincoln Way - Park Avenue)	42	7	6
C7	Terrace Lane (Park Avenue - Camellia Way)	42	7	6
	Thornbridge Drive			
C13	Thornbridge Drive (Lake Park Avenue - Wildginger Court)	42	7	6
C13	Thornbridge Drive (Wildginger Drive - Lake Canyon Avenue)	42	7	6
	Tierra Creek Drive			

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C11	Tierra Creek Drive (Lake Canyon Avenue - Wildbrook Court)	36	6	6
C11	Tierra Creek Drive (Wildbrook Court - Gerling Court)	36	6	6
	Toni Court			
C4	Toni Court (Oakwilde Street)	14	7	2
	Tottenham Court			
C9	Tottenham Court (Maugham Drive)	42	7	6
	Tottenham Drive			
C9	Tottenham Drive (Maugham Drive - Chelsham Avenue)	42	7	6
	Tradepost Trail			
C3	Tradepost Trail (Ranch Road - Chisholm Trail)	42	7	6
	Trafalgar Circle			
C9	Trafalgar Circle (Vauxhall Avenue - Vauxhall Avenue)	42	7	6
	Trakhaner Court			
C13	Trakhaner Court (Pinto Trail Drive)	42	7	6
	Trammel Way			
C9	Trammel Way (Colmore Way - Stenton Way)	42	7	6
	Trent Court			
C6	Trent Court (Emerlad Drive)	42	7	6
	Trent Drive			
C6	Trent Drive (Emerald Drive - Oberlin Drive)	42	7	6
	Trudy Way			
C6	Trudy Way (Oberlin Drive - McFarland Street)	100	0	6
	Tudor Street			
C2	Tudor Street (Kent Street - Cindy lane)	100	0	6
C2	Tudor Street (Cindy Lane - Downing Drive)	100	0	6
C2	Tudor Street (Downing Drive - Dover Drive)	100	0	6
C2	Tudor Street (Dover Street - Terry Street)	100	0	6
C2	Tudor Street (Terry Street - Kandy Street)	100	0	6
C2	Tudor Street (Kandy Street - Kost Road)	100	0	6
	Turnace Court			
C4	Turnace Court (McTucker Drive)	36	6	6
	Twin Cities Road			
C13	Twin Cities Road (East Stockton Boulevard - Bergeron Road)	36	6	6

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C13	Twin Cities Road (Bergeron Road - Fermoy Way)	36	6	6
C13	Twin Cities Road (Fermoy Way - McKenzie Road)	36	6	6
C13	Twin Cities Road (McKenzie Road - Carillion Boulevard)	36	6	6
C13	Twin Cities Road (Carillion Road - Dromoland Court)	36	6	6
C13	Twin Cites Road (Dromoland Court - Park Terrace Drive)	36	6	6
C13	Twin Cities Road (Park Terrace Drive - Marengo Road)	36	6	6
	Twin Hills Drive			
C11	Twin Hills Drive (Emerald Vista Drive - Beaver Park Way)	42	7	6
	Vanduzen Court			
C9	Vanduzen Court (Vintage Oak Avenue)	42	7	6
	Vanstom Court			
C11	Vanstom Court (Doradell Way)	42	7	6
	Vauxhall Avenue			
C9	Vauxhall Avenue (Trafalgar Circle - Speakers Court)	42	7	6
C9	Vauxhall Avenue (Speakers Court - Carillion Boulevard)	42	7	6
C9	Vauxhall Avenue (Carillion Boulevard - Sherborne Court)	42	7	6
C9	Vauxhall Avenue (Sherborne Court - Marnego Road)	42	7	6
	Victorian Park Drive			
C6	Victorian Park Drive (Alice Rae Circle - Oak Avenue)	21	7	3
	Village Run Drive			
C4	Village Run Drive (West E Street - New Hope Road)	35	7	5
	Vineyards Court			
C2	Vineyards Court (Cardosa Drive)	42	7	6
	Vintage Oak Avenue			
C9	Vintage Oak Avenue (Elk Hills Drive - Walnut Avenue)	14	7	2
C9	Vintage Oak Avenue (Walnut Avenue - Poppy Court)	14	7	2
C9	Vintage Oak Avenue (Poppy Court - Rachel Drive)	14	7	2
C9	Vintage Oak Avenue (Rachel Drive - Sugarwood Court)	14	7	2
C9	Vintage Oak Avenue (Sugarwood Court - Summit Lakes Way)	14	7	2
C9	Vintage Oak Avenue (Summit Lakes Way - Cedar Flat Way)	14	7	2
C9	Vintage Oak Avenue (Cedar Flat Way - Carillion Boulevard)	14	7	2
	Wagon Way			
C4	Wagio Way (Big Jake Way - West C Street)	100	0	2

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C4	Wagon Way (West C Street - West E Street)	100	0	2
	Wallington Drive			
C9	Wallingotn Drive (Hamstead Drive - Walworth Drive)	100	0	6
C9	Wallington drive (Walworth Drive - Hamstead Drive)	100	0	6
	Walnut Avenue			
C4	Walnut Avenue (East Stockton Boulevard - Emerlad Vista Drive)	100	0	5
C4	Walnut Avenue (Emerald Vista Drive - Vintage Oak Avenue)	100	0	5
C4	Walnut Avenue (Vintage Oak Avenue - Carillion Boulevard)	100	0	5
C4	Walnut Avenue (Carillion Boulevard - Elk Hills Drive)	100	0	5
C4	Walnut Avenue (Elk Hills Drive - Park Terrace Drive)	100	0	5
C4	Walnut Avenue (Park Terrace Drive - Marengo Road)	100	0	5
	Walworth Drive			
C9	Walworth Drive (Wallington Drive - Hamstead Drive)	100	0	6
	Wamsley Court			
C4	Wamsley Court (Wristen Way)	100	0	6
	Warmwood Court			
C13	Warmwood Court (Lake Park Avenue)	100	0	6
	Waterloo Court			
C9	Waterloo Court (Maugham Drive)	100	0	6
	Waterwood Court			
C13	Waterwood Court (Lake Park Avenue)	100	0	6
	Wendy Hope Drive			
C7	Wendy Hope Drive (North Lincoln Way - Camellia Way)	100	0	6
	WhiteChapel Drive			
C9	WhiteChapel Drive (Maugham Drive - Chelsham Avenue)	100	0	6
	Whitford Court			
C11	Whitford Court (Elk Hills Drive)	100	0	6
	Wicker Way			
C9	Wicker Way (Lyonia Drive - Ashboro Lane)	100	0	6
	Wild Poppy Court			
C13	Wild Poppy Court (Snow iLilly Avenu)	100	0	6
	Wildbrook Court			
C11	Wildbrook Court (Tierra Creek Drive)	100	0	6
	Wilder Way			

Draft

SIDEWALKS PRIORITY RANKING TABLE

Legend:

ADA Deficiency Value
1. No Curb Ramp in a developed area
2. 32" minimum clear passage width not met
3. Missing sidewalk in a developed area
4. Curb ramps without minimum landing pad
5. Obvious areas with sidewalk cross-slope that exceeds 2% (Includes driveways)
6. Curb ramps that do not meet current ADA requirements
7. Sidewalks that do not meet current ADA requirements

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

NOTE: THE LOWER THE PRIORITY NUMBER THE HIGHER THE PRIORITY AND THE MORE SERIOUS THE CONDITIONS
A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C3	Wilder Way (Kost Road - McCauley Way)	100	0	6
	Wildflower Way			
C6	Wildflower Way (Sunshine Drive - Oberlin Drive)	100	0	6
	Wildginger Court			
C13	Wildginger Court (Thornbridge Drive)	100	0	6
	Willowgreen Circle			
C10	Willowgreen Circle (Emerlad Vista drive - Emerlad Vista Drive)	100	0	6
	Winn Drive			
C11	Winn Drive (East Stockton Boulevard - Emerald Vista Drive)	100	0	5
	Wise Way			
C3	Wise Way (McCauley Way - Wilder Way)	100	0	6
	Woodflower Court			
C13	Woodlower Court (Snow lily Avenue)	100	0	6
	Wren Court			
C6	Wren Court (Wren Drive)	100	0	6
	Wristen Way			
C4	Wristen Way (Rio Mesa Way - Allport Drive)	100	0	6

Draft

Draft

TRAFFIC SIGNAL RANKING TABLE

Legend:

ADA Deficiency Value
0. No Signal ADA Deficiency
1. Signal ADA Deficiency

Location Priority Value
1. Access to and around transportation facilities
2. Access to and around government facilities (including schools)
3. Access to and around places of public accommendation
4. Access to and around places of employment
5. Places with high levels of pedestrian travel
6. All other locations

A PRIORITY OF 100 MEANS THAT NO DEFECTS WERE NOTED OR REPAIRS WERE COMPLETED

Atlas Grid	Street Location	Overall Priority	ADA Deficiency	Location Priority Value
C5	C Street / Civic Drive NE	1	1	1
C5	C Street / Lincoln Way SE	2	1	2
C5	Lincoln Way / A Street NE	2	1	2
C7	Lincoln Way / Amador Avenue Standard Intersection Crosswalk N&S	5	1	5

Draft